

**CITYCAB PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO SHC7055K  
 MAKE REG. 26.08.2022  
 MODEL BYD

DATE 29.12.2022  
 CHIANG/INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER / CRC			\$3,301.87
1	REAR BUMPER LOWER COVER / CRC			\$2,013.75
1	REAR BUMPER REINFORCEMENT ?			\$528.75
2	REAR BUMPER REFLECTOR LH/RH ✓ L? R / CRC		\$48.00	\$96.00
1	REAR BUMPER REVERSE LAMP / MIS			\$375.00
2	REAR BUMPER BRACKET LH / RH ?		\$24.00	\$48.00
2	REAR BUMPER RETAINER LH / RH ?		\$87.00	\$174.00
1	TAIL GATE EMBLEM 26 / NEC			\$38.00
1	REAR FLOOR PANEL ?			TBA
	<b>SUB TOTAL</b>			<b>\$6,575.37</b>
	<b>LESS 20%</b>			<b>\$1,315.07</b>
				<b>\$5,260.30</b>
1	REVERSE SENSOR x SVC			\$240.00
1	REAR TAIL GATE APP STICKER / NEC			\$30.00
1	BUMPER LINE STICKER / NEC			\$40.00
1	REAR DOOR ELECTRIC 100 / NEC			\$80.00
				<b>\$351.00</b>
	<b>Labour Charge</b>			
	Panel Beating		1,200	<del>\$1,800.00</del>
	Spray Painting Charge		500	<del>\$700.00</del>
	Remove/Refix Upholstery			<del>\$90.00</del>
	Tuff Coat		40	<del>\$90.00</del>
	Check Wiring		30	<del>\$60.00</del>
	<b>TOTAL LABOUR</b>			<b>\$2,740.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$8,351.29</b>
	NAZ LKK			
	30/12/2022 1620			
	PIP			
	3 DAYS			
	CHECK ITEM PHOTOS			
	BEFORE/AFT PHOTOS			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				