



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI23000072/Rqy3e2

Date: 10/02/2023

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMB 5074P	Veh. Inspected	SBS 6665T
Policy No.	D-22099187MFBP	Coverage (\$)	0.00
Claim No.	D23000070MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	04/01/2023

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CITARO	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WEB62808323125093	Colour	MULTI COLOUR
Odometer	699857 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	PIRELLI	8 mm
L/H Front Tyre	275/70 R22.5	PIRELLI	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	PIRELLI	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	PIRELLI	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/12/2022	Inspection Date	04/01/2023
Survey held at	SBS TRANSIT LTD (Branch) BUKIT BATOK ST 23 SINGAPORE 659519		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **1 Working Days**