



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI23000072/Rqy3

Date: 04/01/2023

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMB 5074P	Veh. Inspected	SBS 6665T
Policy No.		Coverage (\$)	0.00
Claim No.	D23000070MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	04/01/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/12/2022	Inspection Date	04/01/2023
Survey held at	SBS TRANSIT LTD (Branch) BUKIT BATOK ST 23 SINGAPORE 659519		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--