



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000073/Tqy3e2 Date: 04/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 7792B	Veh. Inspected	SNA 7787X	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/0094	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	04/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ SLK 200	c.c	1796	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WDD1724482F020184	Colour	SILVER	
Odometer	70652 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	MICHELIN	6 mm	
L/H Front Tyre	225/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/12/2022	Inspection Date	05/01/2023	
Survey held at	AUTOSPRINT PTE LTD 24 LENG KEE ROAD #07-01/02 LENG KEE AUTOPOINT SINGAPORE 159096			
5a. Remarks				
A)REGISTRATION DATE: 03 NOV 2011 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	