



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMT7808G TOYOTA NOAH 1.8

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>						
1	Boot lid <i>bme</i> ✓	2361 289 <u>1770.75</u>	1719.00		1 X X	
1	Boot lid emblem 'Hybrid synergy drive' <i>an</i> ✓		62.00			
1	Rear bumper <i>de</i> ✓		580.00			
2	Rear bumper clips RH/LH @2*\$231 <i>an</i> X nn		462.00			
1	End panel <i>repair</i>		679.00			
Part Items Total:				3502.00		
			-25%	-875.50		
				2626.50		
<u>SPECIAL NETT ITEMS</u>						
1	Rear windscreen sealant <i>an</i> ✓	<u>40</u>	60.00		60 X	
1	Rear Car plate X nn		35.00			
SN Items Total:			95.00			
Total Parts			2721.50			



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMT7808G TOYOTA NOAH 1.8

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	600.00	40
4	To remove and refit rear windscreen	100.00	
5			
Labour Total :		1560.00	
TOTAL (PARTS & LABOUR):		4281.50	

1770.75

40.00

1340.00

3150.75

20%

2520.60

45 - \$2,500 / 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

6 days

H/S

06/01/23 @ 1110

Resurvey after repair