



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMT7808G TOYOTA NOAH 1.8

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Boot lid <i>bme</i> ✓		1719.00	
1	Boot lid emblem 'Hybrid synergy drive' <i>an</i> ✓		62.00	
1	Rear bumper <i>de</i> ✓		580.00	
2	Rear bumper clips RH/LH @2*\$231 <i>an</i> X		462.00	
1	End panel <i>repair</i>		679.00	
		Part Items Total:	3502.00	
			-25% -875.50	
			2626.50	
	<u>SPECIAL NETT ITEMS</u>			
1	Rear windscreen sealant <i>an</i> ✓		60.00	<i>60</i>
1	Rear Car plate X		35.00	X
		SN Items Total:	95.00	
		Total Parts	2721.50	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMT7808G TOYOTA NOAH 1.8

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00 /	
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00 40	
4	To remove and refit rear windscreen	100.00 /	
5			
Labour Total :		1560.00	
TOTAL (PARTS & LABOUR):		4281.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

6 days

H/S

06/01/23 @ 1110

Resurvey after repair