



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23000079/Avy3m4 Date: 17/02/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 6545G	Veh. Inspected	SKM 9179K
Policy No.		Coverage (\$)	0.00
Claim No.	D23000067MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	04/01/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C 180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2040312A928145	Colour	WHITE
Odometer	149485 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	6 mm
L/H Front Tyre	225/45 R17	PIRELLI	6 mm
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/12/2022	Inspection Date	17/01/2023
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	