

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III23000081/UWY3M4**Date:** 27/02/2023**REFERENCE**

Insured/Claimant: SARIPAH BINTE MOHAMED SHAM SUDDIN Policy No: D19MPC0003729-03

Date of Loss: 31/12/2022

Nature of Claim: OD

Claim No: MPC2023D0000176

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR2784X**
 Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UGB5724
 Reg. Date: 08/08/2017 (Man. Year: 2017) Chassis No: MMBSTA13AHH006333
 Colour: Blue Odometer: 28292 km
 Engine Capacity: 1193 cc
 Market Value/New Car Price: S\$40,000.00
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,873.20	2,026.50	4,846.70	70.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,120.00	830.00	42.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,823.20	3,146.50	5,676.70	64.34
Approved Total (Overridden) (\$\$)		2,500.00		
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	8,223.20	1,900.00	6,323.20	76.89
+ GST 8.00/8.00% (\$\$)	657.86	152.00	505.86	76.89
Nett Amount (\$\$)	8,881.06	2,052.00	6,829.06	76.89

INSPECTION

Date of Assignment: 04/01/2023

Date Inspected: 10/01/2023 Inspected At:

Falcon-Air Auto Services Pte Ltd (Tampines)
Blk 9006 #01-200 Tampines St 93
Singapore 528840

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Feb 2023)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2784X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRONT DOOR	Badly Dented	1,287.00 FN	*899.00 FN
2	1		*O/S FRONT DOOR BLACK STICKER	Necessary	69.00 FN	*69.00 FN
3	1		*O/S FRONT DOOR BOARD	Not Necessary	796.00 FN	*- FN
4	1		*O/S FRONT DOOR RUBBER	Necessary	267.00 FN	*149.00 FN
5	1		*O/S REAR DOOR	Dented/Bent	1,287.00 FN	*851.00 FN
6	1		*O/S REAR DOOR HINGE - TOP	Not Necessary	85.00 FN	*- FN
7	1		*O/S REAR DOOR HINGE - LOWER	Not Necessary	85.00 FN	*- FN
8	1		*O/S REAR DOOR BLACK STICKER	Necessary	69.00 FN	*69.00 FN
9	1		*O/S REAR DOOR BOARD	Not Necessary	796.00 FN	*- FN
10	1		*O/S REAR DOOR RUBBER	Necessary	267.00 FN	*148.00 FN
11	1		*O/S REAR RIM	Not Necessary	1,234.00 FN	*- FN
12	1		*O/S REAR WHEEL BEARING	Not Necessary	354.00 FN	*- FN
13	1		*O/S SIDE MIRROR	Not Necessary	752.00 FN	*- FN
14	1		*O/S FRONT DOOR BODY SEALANT	Not Necessary	80.00 FS	*- FS
15	1		*SET O/S FRONT DOOR BOARD CLIP	Necessary	50.00 FS	*30.00 FS
16	1		*SET O/S REAR DOOR BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*O/S REAR DOOR BODY SEALANT	Not Necessary	80.00 FS	*- FS
					Sub Total (S\$)	7,608.00 2,245.00
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	734.80 218.50
					Total Parts (S\$)	6,873.20 2,026.50

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TRANSFER O/S FRONT DOOR PARTS	New	100.00	50.00
3	TRANSFER O/S REAR DOOR PARTS	New	100.00	50.00
4	LABOUR/PANEL BEATING	New	700.00	400.00
5	SPRAY PAINTING	New	1,000.00	600.00
Gross Labour Cost (\$\$)			1,950.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >