

Vehicle Damage Assessment Report for [SLR2784X]

Estimate Created: 11/01/2023 04:20 by LKK_assignments
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 24/02/2023 14:02 by Insurlogic 5 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	India International Insurance	Claim Number	MPC2023D0000176
Claim Type	OD		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Mitsubishi	Model	Attrage
Engine Type			
License Plate Number	SLR2784X	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on further information provide by LKK: Concluded the cost of repair at lump sum \$2,500.00 with 4 days for repair	Insurlogic 5 (24/02/2023 14:02)
- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$3300.00 with 4 days for repair	Insurlogic 5 (05/02/2023 15:19)
- Pre Review done base on survey information provided Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.	
Pre Review By : Insurlogic Amount : \$4101.40 Lump sum:\$3300.00 Repair Duration: 4 days	Insurlogic 5 (19/01/2023 07:17)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT DOOR RH		1	899.00	-10.00 %	809.10
FRONT DOOR BLACK STICKER RH		1	69.00	-10.00 %	62.10
FRONT DOOR RUBBER RH		1	149.00	-10.00 %	134.10
RH REAR DOOR		1	851.00	-10.00 %	765.90
REAR DOOR BLACK STICKER RH		1	69.00	-10.00 %	62.10
REAR DOOR RUBBER RH		1	148.00	-10.00 %	133.20
Parts Subtotal					1,966.50

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR DOOR BOARD CLIPS RH		1.0	30.00	0.00 %	30.00
FRONT DOOR BOARD CLIPS RH		1.0	30.00	0.00 %	30.00
Materials Subtotal					60.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRIE	RnR	20.00	0.00 %	20.00
TRANSFER FRONT DOOR RH PARTS	RnR	50.00	0.00 %	50.00
TRANSFER REAR DOOR PARTS RH	RnR	50.00	0.00 %	50.00
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	400.00	0.00 %	400.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	600.00	0.00 %	600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 520.00

Paint Labor Subtotal 600.00

Labor Subtotal 1,120.00

Summary

Repair Cost	3,146.50
Discount(20 %)	(629.30)
	2,517.20
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,517.20