

2020 SPRAY PAINTING PTE LTD
8 KAKI BUKI AVENUE 4
#03-19 PREMIER@KAKI BUKIT
SINGAPORE 415875

TP China
Hui Rong

Page No. 1

Vehicle No. SFH1232C

HONDA STREAM

JHMRN68609S200156

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	REAR BUMPER <i>Dehnd</i>		668.40	✓
2	REAR BUMPER SIDE HOLDER @34.10 <i>New</i>		68.20	✓
3	REAR BUMPER TOW COVER <i>Dehnd</i>		39.40	✓
4	REAR END PANEL <i>Dented</i>		459.10	✓
5	REAR END PANEL INNER MEMBER <i>Repair</i>		186.90	X.
6	REAR END PANEL TOP GARNISH <i>Dehnd</i>		216.70	✓
7	TAILLAMP @366.50 <i>Not New</i>		733.00	X.
8	TAILLAMP PANEL @390.10 <i>Not New</i>		780.20	X.
9	TAILGATE <i>Dented</i>		903.40	✓
10	TAILGATE LOCK <i>Dented</i>		189.40	✓
11	TAILGATE WEATHERSTRIPE <i>Not New</i>		195.90	X.
12	TAILGATE DAMPER @212.10 <i>Not New</i>		424.20	X
13	TAILGATE INNER TRIM BOARD <i>Not New</i>		285.10	X.
14	TAILGATE OUTER GARNISH <i>Not New</i>		239.80	X.
15	TAILGATE GLASS MOULDING <i>New</i>		124.10	✓
16	HONDA LOGO <i>New</i>		45.90	X.
17	STREAM WORDING <i>New</i>		49.10	✓
18	FLOOR PANEL TOP COVER @242.10 <i>Not New</i>		482.20	X.
19	REAR FENDER INNER TRIM BOARD @295.40 <i>LH Chuld</i>		590.80	255.40
20	REAR EXHAUST PIPE	3013.20	678.10	X
21	REAR EXHAUST PIPE MOUNTING	2410.56	35.80	X
22	REAR EXHAUST PIPE GASKET		32.60	X
23	REAR EXHAUST HEAT SHIELD		115.90	X
			7544.20	
less			20%	20%
			1508.84	
			6035.36	
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE <i>? Deformed</i>		30.00	✓
2	REAR NUMBER PLATE HOLDER		30.00	✓
3	REAR BUMPER CLIPS <i>New</i>		50.00	30.
4	REVERSE SENSOR <i>Damaged</i>		280.00	200
5	REAR END PANEL TOP GARNISH CLIPS <i>New</i>		20.00	✓
6	REAR END PANEL SEALANT <i>New</i>		60.00	✓
7	TAILGATE INNER TRIM BOARD CLIPS <i>New</i>		30.00	X
8	TAILGATE OUTER GARNISH CLIPS <i>Not New</i>		30.00	X
9	TAILGATE GLASS SEALANT <i>New</i>		60.00	✓
10	REAR FENDER INNER TRIM CLIPS <i>New</i>		60.00	30.
Total Parts			650.00	

2020 SPRAY PAINTING PTE LTD
 8 KAKI BUKI AVENUE 4
 #03-19 PREMIER@KAKI BUKIT
 SINGAPORE 415875

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1200.00 800	
2	SPRAY PAINTING	1200.00 800	
3	WIRING	100.00 30	
4	TO APPLY TUFF COAT	150.00 60	
5	TO REMOVE UPHOLSTERY	150.00 60	
12	TO TRANSFER TAILGATE FITTINGS	150.00 60	
13	TO REMOVE TAILGATE GLASS	180.00 120	
14	TO REMOVE REVERSE SENSOR	100.00 50	
18	TO REMOVE REAR EXHAUST PIPE	150.00 X.	
	Labour Total :	3380.00	1980
TOTAL (PARTS & LABO		10065.36	

total: 4850.56

h/s: 3.8K

05 Days