

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI23000098/KQP3Q2**Date:** 20/03/2023**REFERENCE**

Insured/Claimant: Chia Hsiang Yang Policy No: DMPCSNW00146822204

Date of Loss: 27/12/2022 Nature of Claim: OD Claim No: SNM22D209344/C01/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJG8176T**

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A)

Engine No: 2AZC395722

Reg. Date: 16/07/2008 (Man. Year: 2008)

Chassis No: ACR507060309

Colour: Metallic Green

Odometer: 219053 km

Engine Capacity: 2362 cc

Market Value/New Car Price: S\$8,500.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215 55 R17

Front Left Side: Yokohama 8 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,268.40	6,695.40	573.00	7.88
Miscellaneous Items	150.00	150.00	0.00	0.00
Labour	978.60	974.40	4.20	0.43
Paintwork Labour	676.62	676.62	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,073.62	8,496.42	577.20	6.36
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	9,073.62	6,000.00	3,073.62	33.87
+ GST 8.00/8.00% (S\$)	725.89	480.00	245.89	33.87
Nett Amount (S\$)	9,799.51	6,480.00	3,319.51	33.87

INSPECTION

Date of Assignment: 04/01/2023 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 05/01/2023 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Estimated Period of Repair: 7.0 days 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2023)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG8176T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		7,268.40 F	*6,695.40 F
F=Franchise part.						
Total Parts (S\$)					7,268.40	6,695.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	150.00	150.00
Sub Total (\$\$)			150.00	150.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	676.62	676.62
<u>Labour Items</u>				
2	Total of Labour	New	978.60	974.40
Gross Labour Cost (\$\$)			1,655.22	1,651.02

Report was unsubmitted during this print-out.

< END OF ESTIMATES >