



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: TEO KITTY		Ref: CS/ASM23000106/Uvp3m4 Date: 06/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4340L	Veh. Inspected	SJU 8818B
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04HDK	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	04/01/2023
2. Vehicle Particulars & Condition			
Make & Model	MAZDA CX-9 (A)	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JM6TC4WLAK0311610	Colour	GREY
Odometer	73673 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	265/40 R22	BRIDGESTONE	6 mm
L/H Front Tyre	265/40 R22	BRIDGESTONE	6 mm
R/H Rear Tyre	265/40 R22	BRIDGESTONE	6 mm
L/H Rear Tyre	265/40 R22	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/12/2022	Inspection Date	04/01/2023
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	