

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 02 Feb 2023

**Preliminary Advice**

Insured Vehicle No	: GBH4972C		
TP Vehicle No	: SLL8887A	Accident Date	: 24/12/2022
Make	: MERCEDES-BENZ C200	Assignment Date	: 11/01/2023
Date of Inspection	: 05/01/2023	Est. Duration of Repair	: 3
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,670.55
Revised Amount	:S\$	4,277.95
Check Items (Estimated)	:S\$	4,277.45
Total	:S\$	8,555.40

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.