

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2301-006

DATE : 4-Jan-2023

POLICY NO. : AUTO&GEN P10461765R02

VEHICLE REG. NO. : SGW34Z

VEHICLE MAKE : Mercedes GLA180 (R18 BI)

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 1,450.00	\$ 1,450.00
2	Front Bumper Clip	6	\$ 10.00	\$ 60.00
3	Front Bumper Lower RH	1	\$ 100.00	\$ 100.00
4	Front Bumper Side Retainer RH	1	\$ 60.00	\$ 60.00
5	Front Bumper Side Grille RH	1	\$ 80.00	\$ 80.00
6	Front Bumper Upper Rubber Seal	1	\$ 60.00	\$ 60.00
7	Front Bumper Emblem	1	\$ 60.00	\$ 60.00
8	Front Bumper Basic Carrier RH	1	\$ 100.00	\$ 100.00
9	Head Lamp Unit RH	1	\$ 2,400.00	\$ 2,400.00
10	Head Lamp Nozzle Cover RH	1	\$ 90.00	\$ 90.00
11	Head Lamp Nozzle Cover Spring RH	1	\$ 30.00	\$ 30.00
12	Head Lamp Nozzle Pump RH	1	\$ 180.00	\$ 180.00
13	Front Distance Sensor Wiring Harness	1	\$ 200.00	\$ 200.00
14	Front Distance Sensor @ Bumper Outer RH	1	\$ 240.00	\$ 240.00
15	Front Distance Sensor Decoupling Ring	4	\$ 10.00	\$ 40.00
Total Spare Parts				\$ 5,150.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
16	Spray Paint Front Bumper	1	\$ 300.00	\$ 300.00
17	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 500.00	\$ 500.00
18	Reset and Reprogram Headlamp Replacement	1	\$ 150.00	\$ 150.00
19	Remove, Refit, Replace Front Distance Sensors	1	\$ 70.00	\$ 70.00
20	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,050.00
Amount Before Excess				\$ 6,200.00
Add GST @ 7%				434.00
Total Amount Payable				\$ 6,634.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.