

Section A - Accident Details

Registration Number	SHB5991B
Case Reference Number	TAX/01/23/2005
Registration Date	1/Dec/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LEE SIN SIONG
Type of Accident	Head To Side
Accident Date and Time	4/Jan/2023 10:25 AM
Accident Reported Date and Time	4/Jan/2023 11:34 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117303
Special Instruction to ARC, if any	DAMAGE TO THE RIGHT REAR SIDE OF THE TAXI
Prepared Date and Time	4/Jan/2023 1:25 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,690.00	\$1,000.00
Total Spray Cost	\$1,494.00	\$700.00
Total Spare Part Cost	\$11,057.84	\$6,737.36
Total Other Cost	\$1,190.00	\$370.00
TOTAL COST	\$15,431.84	\$8,807.36 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	12.0	10.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / AIG
ARC / Surveyor Sign Off Date	10/01/2023 1:49 PM	10/01/2023 1:37 PM
Signature		
Remarks	Initial 10 days / sup 2 days / total 12 days	PART BY PART / Before paint photo ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/ EMAIL: taufikh@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0014	Invoice Number	
Quotation Date	02.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,690.00	\$1,000.00 ✓
Total Labour	\$1,690.00	\$1,000.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 ✓
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$1,494.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$50.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00 ✓
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓
TO REMOVE AND REFIX UNDERCARRIAGE	\$250.00	\$150.00 nec ✓
Total Other Costs	\$1,190.00	\$370.00

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Check	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		81457-47020	LENS & BODY, REAR COMBINATION LAMP, NO.2	0.00	\$282.70	0.00	\$0.00	Replace	Not Given	X
		81551-47481	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$367.30	0.00	\$0.00	Replace	Not Given	X
		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
		9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$42.20	0.00	\$0.00	Replace	Not Given	X

X NN

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/02/2023

User ID : PohSuan

	52453-47900	GUARD, RR BUMPER, LOWER	0.00	\$405.00	0.00	\$0.00	Replace	Not Given	X NN
	52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√ NEC
	52591-47080	SEAL, RR BUMPER, RH	0.00	\$128.00	0.00	\$0.00	Replace	Check	X NN
	52575-47060	RETAINER, RR BUMPER, RH	1.00	\$143.60	25.00	\$107.70	Replace	Replace	√ DE
	52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X NN
	52191-47030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace	Replace	√ NEC
	52461-47070	PAD, RR BUMPER, CTR	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X NN
	52462-47020	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√ NEC
	52462-47030	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√ NEC
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Check	X NN
	4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	Replace	√ DD
	61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	Replace	√ BUC
	69803-47020	DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given	X NN
	85720-47150	DOOR REAR MOTOR ASSY, POWER WINDOW	0.00	\$996.60	0.00	\$0.00	Replace	Not Given	X
	52462-47130	PAD, RR BUMPER, RH & LH , 3	2.00	\$12.00	25.00	\$18.00	Replace	Replace	√ NEC
	52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	25.00	\$394.05	Replace	Replace	√ DE
	67003-47211	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	Replace	√ BT
	68630-47050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X
	68750-20122	HINGE ASSY, REAR DOOR, UPPER RH	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X
	68770-52031	HINGE ASSY, REAR DOOR, LOWER RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X
	61017-47010	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	0.00	\$312.10	0.00	\$0.00	Replace	Not Given	X XNN
	6556547010	PATCH, SIDE PANEL REAR END, RH & LH	0.00	\$37.70	0.00	\$0.00	Replace	Check	X
	65637-47060	LINER, REAR FENDER, RH	0.00	\$151.10	0.00	\$0.00	Replace	Check	X
	62940-47010	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$72.40	0.00	\$0.00	Replace	Check	X
	75850-47910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	100.00	\$0.00	Replace	Repair	R
Total				\$10,392.84		\$3,872.93			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52591-47080	SEAL, RR BUMPER, RH	1.00	\$128.00	25.00	\$96.00	Replace	Replace nec
		43550-47020	HUB & BEARING ASSY, RH & LH	1.00	\$722.10	25.00	\$541.58	Replace	Replace bt
		48530-80A03	ABSORBER SET, SHOCK, REAR RH / LH	1.00	\$137.50	25.00	\$103.13	Replace	Replace bt
		48830-47010	LINK ASSY, REAR STABILIZER, RH / LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace bt
		48770-47010	ARM ASSY, UPPER CONTROL, REAR RH	1.00	\$455.00	25.00	\$341.25	Replace	Replace bt
		48730-47010	ARM ASSY, REAR SUSPENSION, NO.2 RH / LH	1.00	\$497.50	25.00	\$373.13	Replace	Replace bt
		42304-47050	CARRIER SUB-ASSY, REAR AXLE, RH	1.00	\$1,025.40	25.00	\$769.05	Replace	Replace bt
		48760-47010	ARM ASSY, TRAILING, REAR RH	1.00	\$400.80	25.00	\$300.60	Replace	Replace bt
		48710-47010	ARM ASSY, REAR SUSPENSION, NO.1 RH / LH	1.00	\$258.60	25.00	\$193.95	Replace	Replace bt
Total					3,819.20		2,864.42		

6,737.36
+ 1000.00
+ 1070.00
8,807.36