

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LEI WAI KEI
BLK 132B HILLVIEW AVE #03-02
SINGAPORE 669605

Contact : 82925859, 81272195

TAX INVOICE

Repair Code : CLM17546

Date in : 03/01/2023

Vehicle Num. : SMQ5936Z

Model : RENAULT SCENIC IV 1.5L DCI AT SR EU6

Chassis/Eng# : VF1RFA00563699305/K9KF649D060314

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER	1	1490.00	1,490.00
REAR BUMPER CENTER BRACKET	1	380.00	380.00
REAR BUMPER LOWER LID	1	765.00	765.00
REAR BUMPER REFLECTOR LAMP L/R	2	330.00	660.00
REAR BUMPER REINFORCEMENT	1	720.00	720.00
REAR BUMPER REVERSE SENSOR	6	269.00	1,614.00
REAR BUMPER REVERSE SENSOR 'O' RING	6	20.00	120.00
REAR BUMPER REVERSE SENSOR HOLDER	6	88.00	528.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS X	1	450.00	450.00
REAR BUMPER SIDE RETAINER L/R	2	120.00	240.00
REAR BUMPER TOP CHROME PLATE	1	630.00	630.00
REAR END PANEL (INNER)	1	978.00	978.00
REAR END PANEL (OUTER)	1	869.00	869.00
REAR END PANEL ANTENNA SENSOR	1	178.00	178.00
REAR END PANEL INNER TOP GARNISH	1	300.00	300.00
REAR EXHAUST GASKET	1	45.00	45.00
REAR EXHAUST HEAT COVER	1	284.00	284.00
REAR EXHAUST RUBBER MOUNTING ?	2	80.00	160.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LEI WAI KEI
 BLK 132B HILLVIEW AVE #03-02
 SINGAPORE 669605

Contact : 82925859, 81272195

TAX INVOICE

Repair Code : CLM17546
 Date in : 03/01/2023
 Vehicle Num. : SMQ5936Z
 Model : RENAULT SCENIC IV 1.5L DCI AT SR EU6
 Chassis/Eng# : VF1RFA00563699305/K9KF649D060314

REAR EXHAUST SILENCER BOX	1	1690.00	1,690.00
REAR FENDER INNER TRIM BOARD L/R	2	699.00	1,398.00
REAR SPARE TYRE PANEL	1	1900.00	1,900.00
REAR SPARE TYRE PANEL TOOL BOX	1	580.00	580.00
REAR SPARE TYRE PANEL TOP BOARD COVER (LOWER)	1	631.00	631.00
REAR SPARE TYRE PANEL TOP BOARD COVER (TOP)	1	698.00	698.00
REAR SPARE TYRE SCREW LOCK	1	98.00	98.00
REAR TAILGATE	1	3800.00	3,800.00
REAR TAILGATE 'LOGO' EMBLEM	1	200.00	200.00
REAR TAILGATE 'SCENIC' EMBLEM	1	180.00	180.00
REAR TAILGATE CAMERA	1	1245.00	1,245.00
REAR TAILGATE HINGES L/R	2	150.00	300.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	2	60.00	120.00
REAR TAILGATE INNER SCREW COVER	6	25.00	150.00
REAR TAILGATE INNER TRIM BOARD	1	670.00	670.00
REAR TAILGATE MECHANISM LOCK	1	350.00	350.00
REAR TAILGATE NUMBER PLATE LAMP L/R	2	105.00	210.00
REAR TAILGATE OUTER CHROME HANDLE	1	480.00	480.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LEI WAI KEI
BLK 132B HILLVIEW AVE #03-02
SINGAPORE 669605

Contact : 82925859, 81272195

TAX INVOICE

Repair Code : CLM17546

Date in : 03/01/2023

Vehicle Num. : SMQ5936Z

Model : RENAULT SCENIC IV 1.5L DCI AT SR EU6

Chassis/Eng# : VF1RFA00563699305/K9KF649D060314

REAR TAILGATE OUTER COVER	1	1350.00	1,350.00
REAR TAILGATE REFLECTOR L/R	2	489.00	978.00
REAR TAILGATE WEATHER STRIP	1	300.00	300.00
REAR TAILLAMP L/R	2	625.00	1,250.00
REAR TAILLAMP LOWER BRACKET L/R	2	190.00	380.00

Subtotal before discount 29,369.00

Percentage discount 0% 0.00

Sub-total 1 29,369.00

REAR BUMPER CENTER BRACKET RIVET - SET	1	80.00	80.00
REAR BUMPER CLIPS - SET	1	80.00	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	40.00	40.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	50.00	100.00
REAR SPARE TYRE PANEL SEALANT	1	120.00	120.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	60.00	60.00
REAR TAILGATE NUMBER PLATE	1	25.00	25.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE WINDSCREEN SEAL	1	80.00	80.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LEI WAI KEI
BLK 132B HILLVIEW AVE #03-02
SINGAPORE 669605

Contact : 82925859, 81272195

TAX INVOICE

Repair Code : CLM17546

Date in : 03/01/2023

Vehicle Num. : SMQ5936Z

Model : RENAULT SCENIC IV 1.5L DCI AT SR EU6

Chassis/Eng# : VF1RFA00563699305/K9KF649D060314

REAR TAILLAMP CLIPS L/R - SET	2	30.00	60.00
Subtotal before discount			775.00
Percentage discount 0%			0.00
Sub-total 2			775.00
Parts-total			30,144.00

LABOUR

To reset system after repair works	400.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,000.00
To apply anti-rust chemical on repaired and replaced panel.	140.00
To remove, reinstall tailgate mechanism and check for function	80.00
Labour Total	4,290.00
Parts & Labour Total	34,434.00

*** This is a computer-generated document which requires no signature.***