



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23000131/Uqy3q2	Date: 17/01/2023
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 7294A	Veh. Inspected	SLN 8554A	
Policy No.	P10428767R01	Coverage (\$)	0.00	
Claim No.	C10019450 /KY	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	05/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZSU600089240	Colour	BLACK	
Odometer	126990 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/55 R18	FALKEN	6 mm	
L/H Front Tyre	255/55 R18	FALKEN	6 mm	
R/H Rear Tyre	255/55 R18	FALKEN	6 mm	
L/H Rear Tyre	255/55 R18	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/12/2022	Inspection Date	05/01/2023	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	