

DATE : 07.01.2023

TO : **ALLIANCE**
 VEHICLE NO : **GM7057P**
 MODEL : **NISSAN NAVARA**
 DATE OF REG : 19.07.2012(30.06.2027)
 CHASSIS : MNTVCUD40A0600006

07 Alliance
 Xiao Chen.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 1,076.20	\$ 1,076.20
2	REAR BUMPER (CHROME) SIDE <i>Distorted</i>	1	\$ 208.60	\$ 208.60
3	REAR BUMPER TOP STEP GARNISH <i>Behind</i>	1	\$ 298.60	\$ 298.60
4	REAR NUMBER PLATE GARNISH <i>Behind</i>	1	\$ 87.40	\$ 87.40
5	REAR NUMBER PLATE LAMP <i>new</i>	1	\$ 71.30	\$ 71.30
6	REAR BUMPER BRACKET <i>new</i>	1	\$ 326.70	\$ 326.70
7	TAIL LAMP LH <i>Crushed</i>	1	\$ 564.30	\$ 564.30
8	TAIL LAMP PANEL LH <i>new</i>	1	\$ 198.40	\$ 198.40
9	REAR SIDE PANEL LH <i>Distorted</i>	1	\$ 2,265.50	\$ 2,265.50
10	TAIL GATE <i>Dented</i>	1	\$ 798.50	\$ 798.50
11	TAIL GATE INNER COVER GARNISH <i>new</i>	1	\$ 3,946.20	\$ 3,946.20
12	TAIL GATE EMBLEM 'NAVARA' <i>new</i>	1	\$ 100.10	\$ 100.10
	TAIL GATE LOGO <i>new</i>	1	\$ 125.60	\$ 125.60
13	TAILGATE CHAIN <i>new</i>	1	\$ 46.50	\$ 46.50
14	TAIL GATE LOCK <i>new</i>	1	\$ 196.70	\$ 196.70
15	TAIL GATE HINGE <i>new</i>	1	\$ 82.50	\$ 82.50
16	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 63.30	\$ 63.30
17	REAR CARGO BED INNER GARNISH <i>new</i>	1	\$ 686.50	\$ 686.50
18	REAR CARGO BED END PANEL <i>new</i>	1	\$ 1,296.60	\$ 1,296.60

479140
 4312266

TOTAL PRICE \$ 12,439.50
 LESS 10% \$ 1,243.95
SUB TOTAL PRICE \$ 11,195.55

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER TOP STEP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	REAR NUMBER PLATE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
5	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00

TO : **ALLIANCE**
 VEHICLE NO : **GM7057P**
 MODEL : **NISSAN NAVARA**
 DATE OF REG : **19.07.2012(30.06.2027)**
 CHASSIS : **MNTVCUD40A0600006**

6	TAIL LAMP PANEL LH SEALANT <i>Not in</i>	1	\$ 60.00	\$ 60.00	+
7	REAR SIDE PANEL LH SEALANT <i>Not in</i>	1	\$ 80.00	\$ 80.00	+
8	REAR SIDE PANEL RAILING LH <i>Not in</i>	1	\$ 450.00	\$ 450.00	+
9	TAIL GATE SEALANT <i>Not in</i>	1	\$ 150.00	\$ 150.00	+
10	TAIL GATE INNER COVER GARNISH CLIP (SET) <i>Not in</i>	1	\$ 50.00	\$ 50.00	+
11	TAIL GATE STICKER '3 PAX' <i>Not in</i>	1	\$ 30.00	\$ 30.00	15
12	TAIL GATE STICKER '70KM' <i>Not in</i>	1	\$ 30.00	\$ 30.00	15
13	REAR CARGO BED INNER GARNISH CLIP (SET)	1	\$ 40.00	\$ 40.00	+
14	REAR CARGO BED END PANEL SEALANT <i>Not in</i>	1	\$ 50.00	\$ 50.00	+
15	REVERSE SENSOR <i>Not in</i>	1	\$ 200.00	\$ 200.00	+
16	REVERSE CAMERA <i>Not in</i>	1	\$ 380.00	\$ 380.00	+

70

TOTAL \$ 1,800.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS, STRAIGHTEN CHASSIS MEMBER	\$ 2,200.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	650
3	TUFF COAT	\$ 250.00	80
4	WIRING CHECK ON TAILAMP	\$ 120.00	30
5	REMOVE AND REFIX REAR RAILING	\$ 180.00	80
6	REMOVE AND REFIX REVERSE CAMERA	\$ 120.00	50 X
7	REMOVE AND REFIX REVERSE SENSOR	\$ 120.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X

1890

TOTAL

\$5,040.00

TOTAL PARTS COST \$ 12,995.55
 TOTAL LABOUR COST \$ 5,040.00
 TOTAL REPAIR COST \$ 18,035.55

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
 1/5 09/01/23

Not Authorised.

06 Dps

Excess: \$600

Claim: 6272-28

HS: SK

(SK)