

利民达摩多



Jementah Motor Works

Blk 14 Defu Lane 10 #01-406
Singapore 539195
H/P : 9299 6636 Fax : 6285 7054

Date : 05-Jan-23

Estimated repair cost of SMW 2793 G Toyota Prius

Qty	Description	Amt S(\$)
	<u>List Items</u>	
1	Rear taillamp - RH	\$ 866.00 x nn
1	Rear bumper	\$ 541.10 999.70 <i>li</i>
1	Rear bumper lower diffuser	\$ 350 552.00 <i>aut</i>
1	Rear bumper reflector - RH	\$ 211.50 x nn
1	Rear bumper side retainer	\$ 86.00 x nn
1	Rear fender -RH	\$ 824.00 <i>Ry</i>
		\$ 3,539.20
	Less 25%	\$ 884.80 <i>891.10</i>
		\$ 2,654.40 <i>668.52</i>

	<u>Special Nett Items</u>	
1	Rear bumper clip (1 set)	\$ 80.00 <i>300</i>
1	Rear reverse sensor (1 set)	\$ 350.00 x nn
1	Rear tyre	\$ 400.00 x nn
1	Rear wheel rim -RH	\$ 750.00 <i>aut 450</i>
		\$ 1,580.00 <i>480</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

<u>S/N</u>	<u>LABOUR CHARGES</u>	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 x nn
2	To remove and refit inner garnishes.	\$ 150.00 x nn
3	To conduct wheel alignment.	\$ 150.00 <i>80</i>
4	To remove and refit quarter glass to assist repair.	\$ 150.00 x nn
5	To apply undercoating.	\$ 100.00 <i>30</i>
6	Panel beating.	\$ 1,400.00 <i>300</i>
7	To re-spray painting on the affected areas.	\$ 1,200.00 <i>400</i>
		\$ 3,230.00 <i>810</i>

Tan Kah 97495744 / 62563531
W/L Resurvey after repair
after 2 weeks
2-3 days

Grand Total :

\$ 7,464.40

668.32
480
810
1958.32
4581550 3 days