

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 10 Jan 2023

Preliminary Advice

Vehicle No	: SKS4001R	Accident Date	: 02/01/2023
Make	: HONDA CIVIC	Policy No.	: DMPCSNW00074462200
Assignment Date	: 04/01/2023	Excess	: S\$750.00
Date of Inspection	: 05/01/2023	Est. Duration of Repair	: 0
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Modifications found fitted on the vehicle.suggest to do investigation.

RePAIRer's Estimate (Gross)	:S\$	N.A.
Revised Amount	:S\$	0.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	23,750.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,250.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Modifications found fitted on the vehicle.suggest to do investigation.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.