

ASS. REC. BY:

REF:

TU / 230001411kp

C

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/vs Trans Cab

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: S1405826K Yr Regn: 11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Prius C.C. 1798

Colour Imp. White / Red A/C: Insured / Std / NI / NA

Sp. Reading 317792 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKB3FU003074998

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / R/Im or

Tyre Size: F: Wandi 195/65R15

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 8 mm

L/Bal. 5 mm

L/Bal. 8 mm

D.O.A. 3/1/23

D.O.I. 5/1/2023

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S 197

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/1/23 11:00 @ 3300d Carbu

Date/Time, File Pass to?

: Prell. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Transportation

S - RS. \$

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

2)

Not Authorised  
C/Sing & 3300h

**Trans-cab Auto Services Pte Ltd**

AAD2301-010

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5826K**

05 JAN 2023

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

05 JAN 2023

**SHD5826K**

JTDKB3FU003074998

200303878K

TOYOTA

PRIUS

03/01/2022

**SNE3067X/III**

01/11/2018

PART	LIST
1 COVER, FRONT BUMPER	\$ Brw 516.00 ✓
1 ABSORBER, FRONT BUMPER ENERGY	\$ Rn 79.60 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R 716.60 X
1 EXTENSION, FRONT BUMPER, LH	\$ Dis 120.10 ✓
1 EMBLEM ASSY, RADIATOR GRILLE	\$ New Rn 90.80 ✓
1 GRILLE SUB-ASSY, RADIATOR	\$ R 346.00 X
1 GRILLE, RADIATOR, LOWER NO.1	\$ Sn 170.10 X
1 COVER, FRONT BUMPER HOLE, LH	\$ Sn 29.30 X
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$ Sn 47.50 X
1 BRACKET, FRONT BUMPER SIDE, LH	\$ R 59.30 X
1 HOOD SUB-ASSY	\$ R 983.10 X
1 LOCK ASSY, HOOD	\$ R 135.00 X
1 HINGE ASSY, HOOD, LH	\$ R 58.90 X
1 HINGE ASSY, HOOD, RH	\$ R 58.90 X
1 LAMP ASSY, FOG, LH	\$ Mfg Rn 951.40 ✓
1 UNIT ASSY, HEADLAMP, LH	\$ Brw 2,637.60 ✓
1 FENDER SUB-ASSY, FRONT LH	\$ R 977.80 X
1 EMBLEM, SIDE PANEL LH	\$ Rn 54.60 ✓
1 LINER, FRONT FENDER, LH	\$ Sn 202.50 X
<b>TOTAL</b>	<b>\$ 8,235.10</b>
<b>25%</b>	<b>\$ 2,058.78</b>
	<b>\$ 6,176.33</b>

**Special Nett**

1 FRT BUMPER CLIP	\$ Rn 65.00 ✓
-------------------	---------------

**Trans-cab Auto Services Pte Ltd**

**AAD2301-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5826K**

1 FENDER CLIP	\$	<i>nn</i> 130.00	X
1 FENDER LINER CLIP	\$	<i>nn</i> 130.00	X
1 FRT LH BUMPER RETAINER CLIP	\$	<i>nn</i> 65.00	X
<b>TOTAL</b>	<b>\$</b>	<b>390.00</b>	

**TOTAL PARTS \$ 6,566.33**

**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *30d*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *44d*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *2d*

**TOTAL \$ 3,590.00**

**Over All Total \$ 10,156.33**

**(PART-BY-PART) Repair Days**

*04 days*

*2 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 878K

### Vehicle Details

Vehicle No.: SHD5826K  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 04 Jan 2023  
Vehicle Make: TOYOTA  
Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)  
Primary Colour: Red  
Manufacturing Year: 2018  
Engine No.: 2ZR2B58173  
Chassis No.: JTDKB3FU003074998  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$26,605.00  
Original Registration Date: 01 Nov 2018  
First Registration Date: 01 Nov 2018  
Transfer Count: 0  
Actual ARF Paid: \$14,247.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 31 Oct 2026  
PARF Rebate Amount: \$10,685.00

### Intended COE Rebate Details

COE Expiry Date: 31 Oct 2026  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 8  
PQP Paid: \$23,736.00  
COE Rebate Amount: \$11,341.00  
**Total Rebate Amount: \$22,026.00**

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jan 2023

OK