

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/CT/23000144/Upe3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SM72979D Yr Regn: 06/04/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: N / S / Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)



Preli. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

5-Jan-23

Our ref : TP/5214/23

Koh Choy Fung

RE : estimate cost for vehicle no : SMT 2979D

1 pc	bootlid	70/201	\$	1,143.70	✓
1 pc	bootlid lock	7W1		399.50	✓
1 pc	bootlid w/strip	70.1		194.70	✓
1 pc	Camry emblem	121		72.40	✓
1 pc	logo emblem	111		72.20	X
1 pc	Hybrid emblem	111		59.10	✓
2 pcs	bootlid hinges	111		484.80	X
2 pcs	bootlid reflectors	CM		583.40	✓
1 pc	bootlid insulator	70.1		594.50	✓
14 pcs	bootlid insulator clips	111	50	77.00	✓
1 pc	bootlid outer handle	111		184.20	X
2 pcs	taillamp	CM		967.00	✓
2 pcs	taillamp garnish	CM		65.20	✓
2 pcs	taillamp holder	111	25	120.00	1 pc
1 pc	camera	111		1,785.10	X
1 pc	rear bumper	7W1		627.00	✓
2 pcs	rear bumper retainers	111	124.30	248.60	✓
1 pc	rear bumper lower spoiler	70.1		393.00	✓
1 pc	rear bumper lh reflector	CM		65.00	✓
10 pcs	rear bumper clips	111		50.00	✓
1 pc	rear bumper reinforcement	70.1		227.10	✓
1 pc	end panel	111		651.00	✓
1 pc	end panel inner garnish	7W1		296.20	✓
1 pc	rear lh fender	70/201		1,153.20	✓
1 pc	rear lh fender inner trim	111	466.10	636.60	✓
1 pc	taillamp lh inner panel	111		155.00	✓
3 pcs	lh taillamp clips	111		24.00	X
1 pc	rear lh fender garnish	70.1		193.50	✓
5 pcs	end panel inner garnish clips	111		25.00	X
1 pc	exhaust pipe	111		735.00	X
2 pcs	exhaust pipe mounting	111		90.00	X
1 pc	spare tyre cardboard	111		559.80	✓
1 pc	spare tyre panel	111		1,123.30	X
				14,056.10	

Not Allowed
5/1/23
L/S # 8000
Weight the rep.
8 days

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186

Tel : 6343-0934 Fax : 6343-0921

Email : jmartauto@gmail.com

Registration No: 201400246D

GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SMT 2979D

Bal brought forward:	\$	14,056.10	
1 pc rear lh air duct 11		37.80	X
		14,093.90	
less 25%		3,523.48	
		10,570.43	
1 pc rear no plate 11		40.00	snett X
1 pc reverse sensor 7m		250.00	200
1 pc rear w/screen gum 1m		50.00	40
1 pc rear w/screen seal 1m		30.00	40
Panel beating & repair chassis member.		2,000.00	1500
Spray painting.		1,800.00	1200
Wiring.		30.00	✓
Rust proofing.		80.00	✓
Upholstery.		120.00	80
Remove & refit rear w/screen.		120.00	✓
Remove & refit exhaust pipe.		80.00	60
		15,170.43	
Plus 8% GST		1,213.63	
		16,384.06	

SD : sixteen thousand three hundred eighty-four & cents six only.

2 91157
252
6836.77
3350
10186-17

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: