

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG23000147/UYA3Q2**Date:** 28/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210040787
Claimant Vehicle No :	SJE3088H	Insured Vehicle No :	SMZ4974Y
Date of Loss:	03/01/2023	Nature of Claim:	TP
		Claim No:	8887162476SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE3088H	Engine No:	2AZC064557
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR507034741
Reg. Date:	25/03/2008 (Man. Year: 2006)	Odometer:	219798 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,638.70	489.75	10,148.95	95.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,020.00	2,330.00	69.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,988.70	1,509.75	12,478.95	89.21
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	13,988.70	1,200.00	12,788.70	91.42
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
(S\$)		1,400.00		
Liabe Amount (50.00%) (S\$)		700.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		726.75		

INSPECTION

Date of Assignment:	05/01/2023	
Date Inspected:	11/01/2023	Inspected At: SPEEDWERKZ PTE LTD (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre Singapore 147807
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Repair	2,398.00 FL	*- FL
2	1		*REAR DOOR HINGES RH	Not Necessary	836.00 FL	*- FL
3	1		*REAR DOOR MOTOR RH	Not Necessary	778.00 FL	*- FL
4	1		*REAR DOOR LOCK ASSY RH	Not Necessary	1,896.00 FL	*- FL
5	1		*REAR DOOR RUBBER RH	Not Necessary	278.00 FL	*- FL
6	1		*REAR DOOR PROTECTOR RH	Deformed / Torn	653.00 FL	*653.00 FL
7	1		*REAR FENDER RH	Repair	1,933.00 FL	*- FL
8	1		*REAR FENDER PROTECTOR RH	Repair	276.00 FL	*- FL
9	1		*REAR BUMPER	Not Necessary	2,138.00 FL	*- FL
10	1		*REAR BUMPER RETAINER	Not Necessary	227.60 FL	*- FL
11	1		*REAR BUMPER REFLECTOR RH	Not Necessary	238.00 FL	*- FL
12	1		*SET SPORT RIM	Repair	1,500.00 FS	*- FS
13	1		*TYRE	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,551.60	653.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,912.90	163.25
Total Parts (\$\$)	10,638.70	489.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	150.00	0.00
2	APPLY ANTI RUST CHEMICAL	New	150.00	0.00
3	REMOVE AND REFIX UPHOLSTERY CUSHION SEAT ,CARPET AND REPAIR SEAT	New	250.00	0.00
4	REMOVE AND REFIX FENDER QUARTER GLASS	New	100.00	0.00
5	PANEL BEATING & REMOVING AND REPLACING NEW PARTS	New	1,500.00	420.00
6	TO SPRAY PAINTING AND ETC	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,350.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >