

SC Auto Industries (S) Pte Ltd (Co.Reg.No:199800107D)

51 Senoko Road, #03-01

Singapore 758133

Tel: 67582222/65719972 Fax: 62576931 Email: Claims@scauto.com.sg

(SUPPLEMENTARY)**INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMB1SNW00014232200	Date of Loss:	27/12/2022
Vehicle Reg. No.:	PC3099R	Driveable?	
Driver Age/Info:	/ FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KIM TRANSPORT SOLUTION PTE LTD		
Driver:	TNG HUI TING		

Make/Model:	TOYOTA HIACE, 3.0 D DX (A)	Vehicle Reg. Date:	03/05/2015
Vehicle Colour:	METALLIC WHITE		
Engine No:	1KDH2010157956	Chassis No:	KDH2010157956
Odometer:	0 KM		

Paint Type:	METALLIC 2K
Total Loss?	NO
Est. Duration of Repair (day)	30

Present Location:	SC AUTO INDUSTRIES (S) PTE LTD (HQ)
-------------------	-------------------------------------

COST OF CLAIMS**Amount**

Parts	4,183.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$)	4,183.00
---------------------------	-----------------

+ GST 8.00% (\$\$)	334.64
---------------------------	---------------

Nett Amount (\$\$)	4,517.64
---------------------------	-----------------

+ Previous Estimates (\$\$)	38,298.20
------------------------------------	------------------

Claim Total (\$\$)	42,815.84
---------------------------	------------------

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 28 Jun 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 D DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	SC Auto Industries (S) Pte Ltd/PC3099R/28/06/2023 09:55	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FAN BLADE distorted	0.00	0.00	*150.00 F
2	1		*AIR CLENER ASSY cracked	0.00	0.00	*960.00 F
3	1		*MEMBER. FRONT CROSS bent	0.00	0.00	*210.00 F
4	2		*GUSSET, FRONT CROSSMEMBER SIDE LH & RH bent	0.00	0.00	*350.00 F
5	1		*FRONT STEP GARNISH missing	0.00	0.00	*495.00 F
6	1		*FAN BLADE 5B distorted	0.00	0.00	*150.00 F
7	2		*REIN,FRT CROSSMEMBER bent	0.00	0.00	*330.00 F
8	2		*RAD GUIDE NO2 LH/RH cracked	0.00	0.00	*190.00 F
9	1		*A/C PIPE NO 1 dented	0.00	0.00	*398.00 F
10	1		*A/C PIPE NO 2 dented	0.00	0.00	*420.00 F
11	1		*A/C COOLER SUCTION HOSE bent	0.00	0.00	*465.00 F
12	1		*A/C PIPE COOLER DISCHARGE bent	0.00	0.00	*365.00 F

F=Franchise part.

Total Parts (S\$)**4,183.00**

SC Auto Industries (S) Pte Ltd/PC3099R/28/06/2023 09:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

SC Auto Industries (S) Pte Ltd/PC3099R/28/06/2023 09:55. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >