COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHD4646U

Make : HYUNDAI

Model : IONIQ(G3)

Date: 20.12.2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER			Cra \$459.40
10	REAR BUMPER CLIPS			Ne = \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			7 \$451.25
1	REAR BUMPER REINFORCEMENT			? \$394.80
1	REAR BUMPER REINFORCEMENT BRACKET RH			7, \$138.10
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	? . \$111.60
1	REAR BUMPER UNDER SIDE COVER RH			Cray \$108.00
1	REAR BUMPER REFLECTOR LAMP RH			Ser \$41.45
1	ASSY BSD BLIND SPOT RADAR RH			7, \$1,784.40
1	ROCKER PANEL GARNISH LH			SIC \$290.00
	SUB TOTAL			\$3,801.00
	LESS 20%			\$760.20
	DISCOUNTED TOTAL			\$3,040.80
	REAR BUMPER RUBBER MAT			\$50.00
	NEAR BOWN ERROBSER WAY		NETT	\$50.00
	Labour Charge			_
	PANEL BEATING			700 \$750.00
	SPRAY PAINTING CHARGE			500 \$600.00
	CHK ALL LIGHTING/ WIRING			30 \$60.00
	TUFF KOTE			xnn \$60.00
	REMOVE/REFIX REVERSE SENSOR			30 \$80.00
	TOTAL LABOUR			\$1,550.00
	ESTIMATE TOTAL			\$4,640.80
				20%
				10/0

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Final=1451.75 21450p

3 days 20/12/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: