MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 6748 4422/ 6745 4422 Fax: 6747- 6720 REG NO 200501102H

Quotation CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD : 02.05.2023 DATE 3 Anson Road #16-00 VEH NO : SME4548E Springleaf Tower : Mazda 3 MODEL Singapore 079909 DOA : 04.01.2023 Tel: 6389 - 6111 YR REF : SMQ8744R Fax: 6224 - 7478 / 7175

Attn: Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SME4548E (MAZDA 3)

Description	Qty	<u>Amt</u>
LIST ITEMS		
Front Bumper Side Holder - LH Md Front Bumper Fog Lamp - LH Hem Front Bumper Fog Lamp Cover - LH Ct Front Bumper Signal Lamp - LH Mem Headlamp - LH Front Fender - LH Devled Front Fender Inner Shield - LH Front Shock Absorber Front Knuckle Arm Front Wheel Hub c/w Bearing Less 20%	1 1 1 1 1 1 4 1 1	1,080.10 40.90 320.50 + 85.50 327.20 + 3,778.20 581.60 162.40 541.30 + 420.40 + 580.50 + 280.90 \$ 8,199.50 (1,639.90) \$ 6,559.60
S/NETT ITEMS Front Bumper Clips	1 set 1 set 1	30.00 30.00 880.00 650 250.00 X,
	Front Bumper Side Holder - LH Md Front Bumper Fog Lamp - LH Men Front Bumper Fog Lamp Cover - LH Cut Front Bumper Signal Lamp - LH Men Headlamp - LH Men Headlamp - LH Devled Front Fender Inner Shield - LH Front Lower Arm Front Shock Absorber Front Knuckle Arm Front Wheel Hub c/w Bearing Less 20% S/NETT ITEMS Front Bumper Clips Front Fender Inner Shield Clips - LH Men Front Wheel Rim - LH At Front Tyre - LH Men	Front Bumper Side Holder - LH Md Front Bumper Fog Lamp - LH Me M Front Bumper Fog Lamp Cover - LH Cut Front Bumper Signal Lamp - LH Me M Front Fender - LH Devled Front Fender Inner Shield - LH Front Lower Arm Front Shock Absorber Front Knuckle Arm Front Wheel Hub c/w Bearing Front Bumper Clips Front Fender Inner Shield Clips - LH Front Tyre - LH Front Md I Front Tyre - LH Front Tyre - LH Front Tyre - LH Front Md I Front Tyre - LH Front Md I Front Tyre - LH Front Tyre - LH Front Tyre - LH Front Md I Front Tyre - LH Front

LABOUR CHARGE

1 To knocking out front left portion & renew above parts

700.00 500

RE: ESTIMATE FOR ACCIDENT REPAIR SME4548E (MAZDA 3)

		Grand Total	\$ 9,749.60
		Total Labour	\$ 2,000.00
6	To perform wheel alignment		\$ 150,00 80
5	To remove front undercarriage	1040	\$ 350.00
4	To apply tuff coat		\$ 150.00 30
3	To check wiring		\$ 50,00 30
2	To putty & spray up paint works		\$ 600,00 400

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

tolul: 6264.72 USI 5 K. DA Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: