



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23000159/Uvy3q2	
			Date: 17/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLD 8564Z	Veh. Inspected	SFM 8138U
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2300038/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLC250 (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDC2533462F640739	Colour	GREY/ BLUE
	Odometer	40417 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	MICHELIN	7 mm
	L/H Front Tyre	235/55 R19	MICHELIN	7 mm
	R/H Rear Tyre	255/50 R19	MICHELIN	7 mm
	L/H Rear Tyre	255/50 R19	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/12/2022	Inspection Date	06/01/2023
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	