



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23000160/Uwy3m4 Date: 09/02/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 3348X	Veh. Inspected	BGT 6034	
Policy No.	D22MTHCVE000882	Coverage (\$)	0.00	
Claim No.	CMTD2204771/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	05/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA UNSER	c.c	1781	
Engine No.	HIDDEN	Year of Reg.	2003	
Chassis No.	PN111KF8104038205	Colour	SILVER	
Odometer	271358 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	TOYO	6 mm	
L/H Front Tyre	185/70 R14	TOYO	6 mm	
R/H Rear Tyre	185/70 R14	TOYO	6 mm	
L/H Rear Tyre	185/70 R14	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2022	Inspection Date	06/02/2023	
Survey held at	1 KAKI BUKIT AVE 6 #01-73 AUTOBAY SINGAPORE 417883			
Repairer	SPEEDWERKZ PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	