

ASS. REC BY: T. J. M.

REF: CS / SMR 23 006 164 / T 73.

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / VS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 4380  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: EDZ728 R. Yr Regn: 2015 April.  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Honda Vezel C.C. 1496  
Colour: White A/C: Insured / Std / NI / NA  
Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: R41101485-2  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 215/60R16  
R: 215/60R16  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
D.O.A. \_\_\_\_\_ D.O.I. 6/1/23  
Survey held at 4wensic motors  
Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
|             | <u>Battery check</u> |
|             | <u>MV-38K</u>        |
|             | <u>Relax: 19471</u>  |
|             | <u>Nett: 418500</u>  |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |
|             |                      |

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / L.B. / % \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS \$ \_\_\_\_\_

Photos

Others

# 4RENSIC MOTORS PTE LTD

8 KAKI BUKIT AVEUNE 4 #01-50, PREMIER @ KAKI BUKIT SINGAPORE 415875

Vehicle number: ED2728R  
 Make and model: Honda Vezel  
 Chassis number: RU11014852  
 Registration Year: 2015

| No. | Description of spare parts                   | Qty  | Amount S\$             |
|-----|--|------|------------------------|
| 1   | Bonnet                                       | 1    | \$ 892.30 <i>bt</i>    |
| 2   | Bonnet RH hinge                              | 1    | \$ 48.50 <i>bt</i>     |
| 3   | Bonnet LH hinge                              | 1    | \$ 48.50 <i>bt</i>     |
| 4   | Bonnet LH rubber stopper                     | 1    | \$ 23.90 <i>x</i>      |
| 5   | Bonnet RH rubber stopper                     | 1    | \$ 23.90 <i>x</i>      |
| 6   | Bonnet inner RH side rubber moulding         | 1    | \$ 38.60 <i>x</i>      |
| 7   | Bonnet inner LH side rubber moulding         | 1    | \$ 38.60 <i>x</i>      |
| 8   | Bonnet inner RH centre rubber moulding       | 1    | \$ 23.00 <i>?</i>      |
| 9   | Bonnet inner LH centre rubber moulding       | 1    | \$ 23.00 <i>?</i>      |
| 10  | Bonnet insulator                             | 1    | \$ 133.40 <i>?</i>     |
| 11  | Bonnet insulator clips                       | 1set | \$ 80.00 <i>?</i>      |
| 12  | Bonnet lock                                  | 1    | \$ 104.50 <i>?</i>     |
| 13  | Bonnet lock cable                            | 1    | \$ 93.20 <i>?</i>      |
| 14  | Bonnet stand                                 | 1    | \$ 78.60 <i>?</i>      |
| 15  | Bonnet stand holder                          | 1    | \$ 18.00 <i>?</i>      |
| 16  | Front bumper                                 | 1    | \$ 801.70 <i>de</i>    |
| 17  | Front bumper clips                           | 1set | \$ 80.00 <i>new 30</i> |
| 18  | Front bumper RH fog lamp                     | 1    | \$ 328.60 <i>?</i>     |
| 19  | Front bumper RH fog lamp bracket             | 1    | \$ 31.20 <i>?</i>      |
| 20  | Front bumper RH fog lamp garnish             | 1    | \$ 47.80 <i>?</i>      |
| 21  | Front bumper LH fog lamp                     | 1    | \$ 328.60 <i>?</i>     |
| 22  | Front bumper LH fog lamp bracket             | 1    | \$ 31.20 <i>?</i>      |
| 23  | Front bumper LH fog lamp garnish             | 1    | \$ 47.80 <i>?</i>      |
| 24  | Front bumper lower grille                    | 1    | \$ 89.30 <i>?</i>      |
| 25  | Front bumper lower spoiler                   | 1    | \$ 389.00 <i>de</i>    |
| 26  | Front bumper lower spoiler clips             | 1set | \$ 80.00 <i>new 20</i> |
| 27  | Front bumper reinforcement                   | 1    | \$ 314.50 <i>?</i>     |
| 28  | Front bumper reinforcement RH moulding       | 1    | \$ 38.70 <i>?</i>      |
| 29  | Front bumper reinforcement RH moulding clips | 1    | \$ 24.00 <i>?</i>      |
| 30  | Front bumper reinforcement LH moulding       | 1    | \$ 38.70 <i>?</i>      |
| 31  | Front bumper reinforcement LH moulding clips | 1    | \$ 24.00 <i>?</i>      |
| 32  | Front bumper towing cover                    | 1    | \$ 18.50 <i>mis</i>    |
| 33  | Front bumper LH side retainer                | 1    | \$ 22.30 <i>de</i>     |
| 34  | Front bumper RH side retainer                | 1    | \$ 22.30 <i>de</i>     |
| 35  | Front grille                                 | 1    | \$ 351.80 <i>new</i>   |
| 36  | Front grille outer upper garnish             | 1    | \$ 103.50 <i>inf</i>   |
| 37  | Front grille chrome moulding                 | 1    | \$ 110.00 <i>inf</i>   |
| 38  | Front grille emblem                          | 1    | \$ 23.50 <i>new</i>    |
| 39  | Front grille emblem clips                    | 1set | \$ 60.00 <i>new 20</i> |
| 40  | Front grille centre bracket                  | 1    | \$ 89.00 <i>?</i>      |
| 41  | Horn low tone                                | 1    | \$ 110.70 <i>?</i>     |
| 42  | Horn high tone                               | 1    | \$ 110.70 <i>?</i>     |
| 43  | RH headlamp                                  | 1    | \$ 1,784.50 <i>de</i>  |
| 44  | RH headlamp lower bracket                    | 1    | \$ 38.00 <i>?</i>      |
| 45  | RH headlamp side bracket                     | 1    | \$ 35.00 <i>?</i>      |
| 46  | LH headlamp                                  | 1    | \$ 1,784.50 <i>de</i>  |
| 47  | LH headlamp lower bracket                    | 1    | \$ 38.00 <i>?</i>      |
| 48  | LH headlamp side bracket                     | 1    | \$ 35.00 <i>?</i>      |
| 49  | Support panel                                | 1    | \$ 675.30 <i>?</i>     |
| 50  | Support panel cover                          | 1    | \$ 156.70 <i>?</i>     |
| 51  | Support panel cover clips                    | 1set | \$ 60.00 <i>?</i>      |
| 52  | Air duct                                     | 1    | \$ 157.80 <i>?</i>     |
| 53  | Air cleaner box lower cover                  | 1    | \$ 189.00 <i>?</i>     |
| 54  | Air cleaner box upper cover                  | 1    | \$ 90.10 <i>?</i>      |
| 55  | Aircon condenser                             | 1    | \$ 578.90 <i>?</i>     |

|     |  |      |    |          |       |
|-----|--|------|----|----------|-------|
| 56  | Aircon discharge pipe                    | 1    | \$ | 213.00   | ?     |
| 57  | Aircon suction pipe                      | 1    | \$ | 198.70   | ?     |
| 58  | Aircon liquid pipe                       | 1    | \$ | 198.20   | ?     |
| 59  | Aircon fan motor                         | 1    | \$ | 298.00   | ?     |
| 60  | Aircon fan blade                         | 1    | \$ | 78.60    | ?     |
| 61  | Aircon fan cowl                          | 1    | \$ | 128.90   | ?     |
| 62  | Radiator assy                            | 1    | \$ | 1,376.80 | ?     |
| 63  | Radiator RH lower rubber mounting        | 1    | \$ | 14.50    | ?     |
| 64  | Radiator LH lower rubber mounting        | 1    | \$ | 14.50    | ?     |
| 65  | Radiator RH upper rubber mounting        | 1    | \$ | 10.50    | ?     |
| 66  | Radiator LH upper rubber mounting        | 1    | \$ | 10.50    | ?     |
| 67  | Radiator fan blade                       | 1    | \$ | 78.60    | ?     |
| 68  | Radiator fan cowl                        | 1    | \$ | 128.60   | ?     |
| 69  | Radiator fan motor                       | 1    | \$ | 298.00   | ?     |
| 70  | Radiator lower hose                      | 1    | \$ | 45.30    | ?     |
| 71  | Radiator upper hose                      | 1    | \$ | 38.70    | ?     |
| 72  | Radiator RH side garnish                 | 1    | \$ | 34.20    | ?     |
| 73  | Radiator LH side garnish                 | 1    | \$ | 34.20    | ?     |
| 74  | Radiator spare tank                      | 1    | \$ | 120.30   | ?     |
| 75  | Radiator upper filler hose               | 1    | \$ | 29.90    | ?     |
| 76  | Front audible speaker                    | 1    | \$ | 89.60    | ?     |
| 77  | Gearbox LH mounting                      | 1    | \$ | 337.10   | ?     |
| 78  | Gearbox LH mounting bracket              | 1    | \$ | 110.00   | x     |
| 79  | Engine RH mounting                       | 1    | \$ | 168.60   | x     |
| 80  | Engine RH mounting bracket               | 1    | \$ | 98.00    | x     |
| 81  | Engine centre mounting                   | 1    | \$ | 178.10   | x     |
| 82  | Engine centre mounting bracket           | 1    | \$ | 102.00   | ?     |
| 83  | Engine under cover                       | 1    | \$ | 98.20    | ?     |
| 84  | Engine under cover clips                 | 1set | \$ | 80.00    | ?     |
| 85  | Engine LH under cover                    | 1    | \$ | 89.10    | ?     |
| 86  | Engine LH under cover clips              | 1set | \$ | 80.00    | ?     |
| 87  | Engine RH under cover                    | 1    | \$ | 89.10    | ?     |
| 88  | Engine RH under cover clips              | 1set | \$ | 80.00    | ?     |
| 89  | Engine intake manifold                   | 1    | \$ | 564.10   | !     |
| 90  | Engine intake manifold hose              | 1    | \$ | 28.70    | ?     |
| 91  | Engine thermostat cover                  | 1    | \$ | 88.10    | ?     |
| 92  | Engine oil dip stick                     | 1    | \$ | 22.70    | ?     |
| 93  | Front fuse box                           | 1    | \$ | 89.00    | ?     |
| 94  | Front fuse box cover                     | 1    | \$ | 66.00    | ?     |
| 95  | Front wire harness                       | 1    | \$ | 2,008.90 | ?     |
| 96  | Front resonator box                      | 1    | \$ | 180.90   | ?     |
| 97  | Front RH fender                          | 1    | \$ | 587.70   | ?     |
| 98  | Front RH fender splash shield            | 1    | \$ | 134.00   | ?     |
| 99  | Front RH fender splash shield clips      | 1set | \$ | 70.00    | ?     |
| 100 | Front RH fender arch moulding            | 1    | \$ | 223.90   | dl    |
| 101 | Front RH fender arch moulding clips      | 1    | \$ | 70.00    | 2over |
| 102 | Front LH fender                          | 1    | \$ | 587.70   | Ry    |
| 103 | Front LH fender splash shield            | 1    | \$ | 134.00   | ?     |
| 104 | Front LH fender splash shield clips      | 1set | \$ | 70.00    | ?     |
| 105 | Front LH fender arch moulding            | 1    | \$ | 223.90   | dl    |
| 106 | Front LH fender arch moulding clips      | 1    | \$ | 70.00    | 2over |
| 107 | Front outside temperature sensor         | 1    | \$ | 89.00    | ?     |
| 108 | Front outside temperature sensor bracket | 1    | \$ | 27.50    | ?     |
| 109 | Washer tank                              | 1    | \$ | 89.00    | ?     |
| 110 | Washer tank motor                        | 1    | \$ | 55.30    | x     |
| 111 | Front windscreen glass                   | 1    | \$ | 1,135.60 | x     |
| 112 | Front windscreen glass rubber moulding   | 1    | \$ | 131.80   | x     |
| 113 | Front wiper garnish                      | 1    | \$ | 255.00   | ?     |
| 114 | Front RH wiper garnish side cover        | 1    | \$ | 25.50    | ?     |
| 115 | Front LH wiper garnish side cover        | 1    | \$ | 25.50    | x     |
| 116 | Front LH airbag sensor                   | 1    | \$ | 187.30   | aut   |
| 117 | Front RH airbag sensor                   | 1    | \$ | 187.30   | aut   |
| 118 | Airbag control unit                      | 1    | \$ | 1,895.10 | aut   |
| 119 | Steering airbag                          | 1    | \$ | 1,605.00 | aut   |
| 120 | Steering airbag spiral sensor            | 1    | \$ | 298.90   | aut   |
| 121 | Dashboard LH airbag                      | 1    | \$ | 2,246.80 | aut   |



|     |   |      |    |          |     |
|-----|---|------|----|----------|-----|
| 122 | Dashboard                                   | 1    | \$ | 832.10   | del |
| 123 | Driver seat belt                            | 1    | \$ | 687.40   | del |
| 124 | Driver seat belt buckle                     | 1    | \$ | 185.00   | X   |
| 125 | Front LH passenger seat belt                | 1    | \$ | 687.40   | del |
| 126 | Front LH passenger seat belt buckle         | 1    | \$ | 185.00   | X   |
| 127 | Rear LH passenger seat belt                 | 1    | \$ | 633.80   | X   |
| 128 | Rear LH passenger seat belt buckle          | 1    | \$ | 185.00   | X   |
| 129 | Rear RH passenger seat belt                 | 1    | \$ | 633.80   | X   |
| 130 | Rear RH passenger seat belt buckle          | 1    | \$ | 185.00   | X   |
| 131 | Tailgate                                    | 1    | \$ | 987.50   | del |
| 132 | Tailgate windscreen glass                   | 1    | \$ | 1,055.30 | del |
| 133 | Tailgate windscreen glass RH rubber seal    | 1    | \$ | 51.00    | del |
| 134 | Tailgate windscreen glass RH rubber seal    | 1    | \$ | 51.00    | del |
| 135 | Tailgate windscreen glass upper rubber seal | 1    | \$ | 51.00    | del |
| 136 | Tailgate windscreen glass lower rubber seal | 1    | \$ | 51.00    | del |
| 137 | Tailgate windscreen glass RH side garnish   | 1    | \$ | 78.50    | del |
| 138 | Tailgate windscreen glass LH side garnish   | 1    | \$ | 78.50    | del |
| 139 | Tailgate windscreen glass upper garnish     | 1    | \$ | 93.20    | del |
| 140 | Tailgate wiper motor                        | 1    | \$ | 603.40   | ?   |
| 141 | Tailgate wiper arm                          | 1    | \$ | 87.00    | del |
| 142 | Tailgate wiper arm cover                    | 1    | \$ | 18.20    | del |
| 143 | Tailgate wiper blade                        | 1    | \$ | 45.60    | del |
| 144 | Tailgate outer garnish                      | 1    | \$ | 256.80   | del |
| 145 | Tailgate outer garnish clips                | 1set | \$ | 80.00    | del |
| 146 | Tailgate outer garnish emblem               | 1    | \$ | 58.00    | del |
| 147 | Tailgate outer garnish emblem clips         | 3    | \$ | 18.50    | del |
| 148 | Tailgate reverse camera                     | 1    | \$ | 1,035.00 | del |
| 149 | Tailgate "Vezel" emblem                     | 1    | \$ | 58.70    | del |
| 150 | Tailgate RH lamp assy                       | 1    | \$ | 487.60   | del |
| 151 | Tailgate RH lamp gasket                     | 1    | \$ | 23.00    | del |
| 152 | Tailgate LH lamp assy                       | 1    | \$ | 487.60   | del |
| 153 | Tailgate LH lamp gasket                     | 1    | \$ | 23.00    | del |
| 154 | Tailgate pull garnish handle                | 1    | \$ | 32.20    | del |
| 155 | Tailgate inner trim board                   | 1    | \$ | 189.90   | del |
| 156 | Tailgate inner trim board clips             | 1set | \$ | 80.00    | del |
| 157 | Tailgate lock                               | 1    | \$ | 189.30   | ?   |
| 158 | Tailgate lock catch                         | 1    | \$ | 33.00    | ?   |
| 159 | Tailgate weatherstrip                       | 1    | \$ | 223.40   | ?   |
| 160 | Tailgate RH hinge                           | 1    | \$ | 93.20    | del |
| 161 | Tailgate LH hinge                           | 1    | \$ | 93.20    | del |
| 162 | Tailgate RH damper                          | 1    | \$ | 202.10   | del |
| 163 | Tailgate LH damper                          | 1    | \$ | 202.10   | ?   |
| 164 | Tailgate spoiler                            | 1    | \$ | 843.20   | del |
| 165 | Tailgate spoiler brake light                | 1    | \$ | 198.30   | del |
| 166 | Tailgate RH number plate lamp               | 1    | \$ | 77.90    | del |
| 167 | Tailgate LH number plate lamp               | 1    | \$ | 77.90    | del |
| 168 | Tailgate outer handle                       | 1    | \$ | 134.20   | del |
| 169 | Rear bumper                                 | 1    | \$ | 512.70   | del |
| 170 | Rear bumper clips                           | 1set | \$ | 80.00    | del |
| 171 | Rear bumper centre garnish                  | 1    | \$ | 288.00   | del |
| 172 | Rear bumper RH reflector                    | 1    | \$ | 141.50   | ?   |
| 173 | Rear bumper LH reflector                    | 1    | \$ | 141.50   | ?   |
| 174 | Rear bumper lower cover                     | 1    | \$ | 250.00   | ?   |
| 175 | Rear bumper RH side retainer                | 1    | \$ | 28.90    | del |
| 176 | Rear bumper LH side retainer                | 1    | \$ | 28.90    | del |
| 177 | Rear bumper RH side cover                   | 1    | \$ | 196.00   | del |
| 178 | Rear bumper LH side cover                   | 1    | \$ | 196.00   | del |
| 179 | End panel                                   | 1    | \$ | 438.00   | ?   |
| 180 | End panel inner garnish                     | 1    | \$ | 98.30    | ?   |
| 181 | End panel inner garnish clips               | 1set | \$ | 40.00    | ?   |
| 182 | End panel antenna sensor                    | 1    | \$ | 78.30    | ?   |
| 183 | End panel buzzer sensor                     | 1    | \$ | 89.00    | ?   |
| 184 | RH taillamp assy                            | 1    | \$ | 488.90   | del |
| 185 | RH taillamp gasket                          | 1    | \$ | 23.00    | del |
| 186 | RH taillamp lock clips                      | 1set | \$ | 22.00    | ?   |
| 187 | RH taillamp panel                           | 1    | \$ | 156.00   | del |

|  |      |    |          |               |
|--|------|----|----------|---------------|
| 188 LH taillamp assy                       | 1    | \$ | 488.90   | <i>bu</i>     |
| 189 LH taillamp gasket                     | 1    | \$ | 23.00    | <i>wa</i>     |
| 190 LH taillamp lock clips                 | 1set | \$ | 22.00    | <i>x</i>      |
| 191 LH taillamp panel                      | 1    | \$ | 156.00   | <i>bu</i>     |
| 192 RH rear fender                         | 1    | \$ | 884.70   | <i>bu</i>     |
| 193 RH rear fender quarter garnish         | 1    | \$ | 74.30    | <i>x</i>      |
| 194 RH rear fender arch moulding           | 1    | \$ | 195.00   | <i>de</i>     |
| 195 RH rear fender arch moulding clips     | 1set | \$ | 70.00    | <i>new 20</i> |
| 196 RH rear fender splash shield           | 1    | \$ | 156.00   | <i>?</i>      |
| 197 RH rear fender splash shield clips     | 1set | \$ | 70.00    | <i>?</i>      |
| 198 RH rear fender upper garnish           | 1    | \$ | 94.30    | <i>?</i>      |
| 199 RH rear fender upper garnish clips     | 1set | \$ | 60.00    | <i>?</i>      |
| 200 RH rear fender inner trim board        | 1    | \$ | 311.00   | <i>?</i>      |
| 201 RH rear fender inner trim board clips  | 1set | \$ | 80.00    | <i>?</i>      |
| 202 LH rear fender                         | 1    | \$ | 884.70   | <i>bu</i>     |
| 203 LH rear fender quarter garnish         | 1    | \$ | 74.30    | <i>de</i>     |
| 204 LH rear fender arch moulding           | 1    | \$ | 195.00   | <i>de</i>     |
| 205 LH rear fender arch moulding clips     | 1set | \$ | 70.00    | <i>new 20</i> |
| 206 LH rear fender splash shield           | 1    | \$ | 156.00   | <i>?</i>      |
| 207 LH rear fender splash shield clips     | 1set | \$ | 70.00    | <i>?</i>      |
| 208 LH rear fender upper garnish           | 1    | \$ | 94.30    | <i>?</i>      |
| 209 LH rear fender upper garnish clips     | 1set | \$ | 60.00    | <i>?</i>      |
| 210 LH rear fender inner trim board        | 1    | \$ | 311.00   | <i>?</i>      |
| 211 LH rear fender inner trim board clips  | 1set | \$ | 80.00    | <i>?</i>      |
| 212 Rear floor compartment panel           | 1    | \$ | 668.70   | <i>?</i>      |
| 213 Rear floor compartment top cover board | 1    | \$ | 493.00   | <i>?</i>      |
| 214 Rear floor compartment sponge tray     | 1    | \$ | 211.00   | <i>?</i>      |
| 215 Exhaust silencer                       | 1    | \$ | 537.00   | <i>?</i>      |
| 216 Exhaust silencer gasket                | 1    | \$ | 49.00    | <i>?</i>      |
| 217 Rear EDLC module battery               | 1    | \$ | 1,043.90 | <i>?</i>      |
| 218 Roof lining                            | 1    | \$ | 1,080.90 | <i>?</i>      |
| 219 Roof lining clips                      | 1set | \$ | 150.00   | <i>?</i>      |

|                   |           |
|-------------------|-----------|
| \$                | 54,307.00 |
| Parts less 20% \$ | 10,861.40 |
| Total: \$         | 43,445.60 |

| No. | Special Nett Items                         | Qty  | Amount S\$          |
|-----|--|------|---------------------|
| 1   | Front windscreen glass sealant             | 1    | 8.00 <i>x</i>       |
| 2   | Front windscreen glass inner seal          | 1    | 60.00 <i>x</i>      |
| 3   | Front windscreen glass ERP bracket         | 1    | 26.00 <i>x</i>      |
| 4   | Front windscreen glass solar flim          | 1    | 450.00 <i>x</i>     |
| 5   | Front number plate                         | 1    | 80.00 <i>450uf</i>  |
| 6   | Radiator coolant                           | 1    | 80.00 <i>?</i>      |
| 7   | Rear number plate                          | 1    | 80.00 <i>450uf</i>  |
| 8   | Tailgate windscreen glass sealant          | 1    | 80.00 <i>40uf</i>   |
| 9   | Tailgate windscreen glass inner seal       | 1    | 60.00 <i>30uf</i>   |
| 10  | Rear bumper reverse sensor                 | 1set | 350.00 <i>200uf</i> |
| 11  | End panel joint sealant                    | 1    | 80.00 <i>40uf</i>   |
| 12  | RH taillamp panel joint sealant            | 1    | 50.00 <i>40uf</i>   |
| 13  | LH taillamp panel joint sealant            | 1    | 50.00 <i>40uf</i>   |
| 14  | RH rear fender joint sealant               | 1    | 80.00 <i>40uf</i>   |
| 15  | LH rear fender joint sealant               | 1    | 80.00 <i>40uf</i>   |
| 16  | Rear floor compartment panel joint sealant | 1    | 120.00 <i>160</i>   |

|           |          |
|-----------|----------|
| Total: \$ | 1,734.00 |
|-----------|----------|

| No.  | Labour and painting  | Amount S\$          |
|--|--|---------------------|
| <b>(front portion)</b>                         |  |                     |
| 1  | Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas | \$ 700 2,600.00     |
| 2  | Spray painting on affected areas and panels  | \$ 800 1,800.00     |
| 3  | Check wiring and lighting system on affected areas   | \$ 30 100.00        |
| 4  | Apply rust coating chemical on affected areas and panels   | \$ 40 150.00        |
| 5  | Remove and replace front windscreen glass to assist repair   | \$ X 240.00         |
| 6  | Remove and replace front dashboard and all dashboard attachments to assist repair  | \$ 200 500.00       |
| 7  | Remove and replace airbags, seat belts, seat belt buckles and airbag sensors to assist repair  | \$ 250 450.00       |
| 8  | Reset and diagnose control unit and fault codes  | \$ 150 550.00       |
| 9  | Remove and replace aircon condenser, pipes and fan assy to assist repair   | \$ 100 ? 250.00     |
| 10   | Remove and replace radiator assy, hoses and fan assy to assist repair  | \$ 200 ? 250.00     |
| 11   | Remove and replace front wire harness and sensors to assist repair   | \$ X 450.00         |
| 12   | Mount vehicle on chassis alignment bench to repair chassis frames  | \$ p/w 200 ? 550.00 |
| 13   | Remove and replace engine mountings, gearbox mountings and brackets to assist repair   | \$ 150 ? 250.00     |
| <b>(rear portion)</b>                          |  |                     |
| 1  | Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas | \$ 1400 3,400.00    |
| 2  | Spray painting on affected areas and panels  | \$ 1300 2,200.00    |
| 3  | Check wiring and lighting system on affected areas   | \$ 30 120.00        |
| 4  | Apply rust coating chemical on affected areas and panels   | \$ 50 180.00        |
| 5  | Remove and reinstall tailgate windscreen glass to assist repair  | \$ 120 220.00       |
| 6  | Remove and replace tailgate reverse camera to assist repair  | \$ 30 120.00        |
| 7  | Remove and replace tailgate inner mechanism to new tailgate  | \$ 60 150.00        |
| 8  | Remove and replace rear bumper reverse sensors   | \$ 30 120.00        |
| 9  | Remove and replace rear inner trims, garnish and boards to assist repair   | \$ 60 320.00        |
| 10   | Remove and replace exhaust silencer and gasket to assist repair  | \$ 80 ? 180.00      |
| Total:   |  | \$ 15,150.00        |
| Agreed Amount: _____ (Part by Part / Lump sum) |  |                     |
| Working days: _____                            |  |                     |
| Spare Parts:                                   |  | \$ 43,445.60        |
| Special Nett:                                  |  | \$ 1,734.00         |

Labour: \$

15,150.00

Total Amount: \$

60,329.60

Tanjilun 774 15749

'WP' 6/1/23 @ 12pm

L/S Resurvey after repair

\$400 15 days

- To check consistency of accident
- To check part prices.
- To check repair limit.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 430Z

### Vehicle Details

Vehicle No.: ED2728R  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 05 Jan 2023  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X A  
Primary Colour: White  
Manufacturing Year: 2014  
Engine No.: L15B3514864  
Chassis No.: RU11014852  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$18,887.00  
Original Registration Date: 17 Apr 2015  
First Registration Date: 17 Apr 2015  
Transfer Count: 0  
Actual ARF Paid: \$8,887.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 16 Apr 2025  
PARF Rebate Amount: \$5,332.00

### Intended COE Rebate Details

COE Expiry Date: 16 Apr 2025  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$62,002.00  
COE Rebate Amount: \$14,139.00  
**Total Rebate Amount: \$19,471.00**

The information contained herein is correct as at 05 Jan 2023

OK



VEHICLE NO: ED 2728R.

MAKE &amp; MODEL: HONDA VEREL. AUTO/MANUAL

|  |  |                                |
|--|--|--------------------------------|
| DATE OF ACCIDENT   | 04/01/23.  | C.C. 1.5.                      |
| TIME OF ACCIDENT   | 0905.  | AM/PM                          |
| LOCATION OF ACCIDENT   | BKE C18) BEF BUKIT PANJANG RD (X1)                     |                                |
| EXACT PURPOSE USED AT TIME OF ACCIDENT   | EMPLOYMENT / PRIVATE USE / PRIVATE HIRE                |                                |
| NAME OF OWNER  | NG ENG HOCK.   |                                |
| EMAIL  | gin988ng@gmail.com                                     | OFFICE: MOBILE: 9686 4199.     |
| NRIC   | S17294302.   |                                |
| CLAIM TYPE   | OD / THIRTY PARTY / REPORTING ONLY                     |                                |
| FLEET POLICY   | YES / NO?  |                                |
| INCURANCE CO.  | msig.  |                                |
| TYPE OF COVERAGE   | Comprehensive / Third Party / Third Party Fire & Theft |                                |
| POLICY NO.   | H 300560092 QNY.                                       |                                |
| NAME OF DRIVER   | AS ABOVE / IF NO: LIM POH CHENG.                       |                                |
| NRIC   | S68174936.   |                                |
| DATE OF BIRTH  | 09/05/68.  |                                |
| ANY PASSENGER  | YES / NO: DRIVER ONLY                                  |                                |
| NAME OF PASSENGER  |  |                                |
| GENDER OF PASSENGER  | MALE / FEMALE  |                                |
| OCCUPATION   | Outdoor / Indoor                                       |                                |
| DATE OF DRIVING PASS   | 13/02/19.  |                                |
| GENDER   | MALE / FEMALE  |                                |
| CONTACT NO.  | Mobile: 7853386 Office: Home:                          |                                |
| EMAIL  | IRIS@NBSGROUP.SG.                                      |                                |
| ADDRESS  | 80 SPRINGLEAF AVE S(788 479).                          |                                |
| DOES DRIVER OWN OTHER VEHICLES?  | NO / If yes, Reg No INSURE: -                          |                                |
| RELATIONSHIP   | Employee / If No: SPOUSE.                              |                                |
| WEATHER CONDITION  | Clear / Raining / Other:                               |                                |
| ROAD SURFACE   | Dry / Wet / Other:                                     |                                |
| ANY INJURIES   | No / If yes, Who? VEH A - DRIVER - SERIOUS.            |                                |
| CONTACT NO.  |  |                                |
| ROLICE REPORT  | No / If yes, Where?                                    |                                |
| NOTICE OF INTENDED PROSECUTION?  | No / If yes, Who?                                      |                                |
| VEHICLE B NO.  | SG 5417L.  | Any Passenger: DRIVER          |
| NAME   |  | UNKNOWN PASSENGER.             |
| CONTACT NO.  |  |                                |
| VEHICLE C NO.  | SG 5878P.  | Any Passenger: DRIVER, UNKNOWN |
| VEHICLE D NO.  |  | Any Passenger: PASSENGER.      |
| VEHICLE E NO.  |  | Any Passenger:                 |
| VEHICLE F NO.  |  | Any Passenger:                 |
| ANY WITNESS  |  |                                |
| WITNESS CONTACT NO.  |  |                                |
| WAS THERE ANY VIDEO CAPTURE?   |  | YES / NO                       |
| WAS THERE ANY AUDIO RECORDED?  |  | YES / NO                       |
| SCENE ACCIDENT PHOTOS TAKEN?   |  | YES / NO                       |
| WHO IS REPORTING   | DRIVER / OWNER / BOTH                                  |                                |
| Original Language Used   | English / Mandarin / Others:                           |                                |
| Have you been approach by unknown person soliciting (s) / offering accident claims assistance? |  | YES / NO.                      |

GINA88NG @ Gmail.com

9686 4199.

IRIS@NBSGROUP.COM.SG.

9685386.



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



