

ASS. REC. BY:

REF:

AG2/2300167/kny3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SLK 66567

Yr Regn:

01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C.

1496

Colour

M-Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

62700

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Ru1

1208291

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

S

mm

Rear

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

3/1/23

D.O.I.

6/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ CH not ready

10/1/23 @ 40000 Cntr (Red, \$4422.80, 53%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 28/4/23

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trlp: _____

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA VEZEL
 Engine/Chassis No.: RU11208291
 Date of accident: 03.01.23
 Damaged area: N/S

Date: 06/01/2023
 Claim Type: TP
 VRN: SLK6656T

Not Authorised
6/1/23 @ 4000h
Recovery After Paint
4 days



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front fender n/s	1	\$ 702.00	\$ 702.00
2	Front fender cowling n/s	1	\$ 185.00	\$ 185.00
3	Front fender splash guard n/s	1	\$ 76.00	\$ 76.00
4	Front bumper <i>CATe marker</i> <i>MS D11</i>	1	\$ 976.00	\$ 976.00
5	Front bumper retainer	2	\$ 85.00	\$ 170.00
6	Front lower arm n/s	1	\$ 421.00	\$ 421.00
7	Front shock absorber n/s	1	\$ 355.00	\$ 355.00
8	Front shock absorber top mount n/s	1	\$ 53.00	\$ 53.00
9	Front wheel knuckle n/s	1	\$ 365.00	\$ 365.00
10	Front wheel knuckle bearing n/s <i>184</i>	1	\$ 266.00	\$ 266.00
11	Front stabilizer end link n/s	1	\$ 115.00	\$ 115.00
12	Front fender arch garnish n/s <i>198.70</i> <i>MS D11</i>	1	\$ 296.00	\$ 296.00
13	Headlamp n/s <i>1859</i> <i>MS</i>	1	\$ 2,256.00	\$ 2,256.00
Subtotal				\$ 6,236.00
List discount				20.00%
Total				\$ 4,988.80

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front alloy wheel n/s <i>MS</i>	1	\$ 550.00	\$ 550.00
2	Front tyre n/s	1	\$ 280.00	\$ 280.00
3	Front bumper clips	12	\$ 5.50	\$ 66.00
4	Front fender cowling clips n/s	8	\$ 5.50	\$ 44.00
5	Front fender arch garnish clips n/s	8	\$ 5.50	\$ 44.00
6	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,034.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect wire harness and electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00
3	To undercoat all affected portions after repair.	1	\$ ~ 200.00
4	To remove and refit n/s front tyre & rim for replacement. To perform tyre balancing.	0.25	\$ 50.00
5	To remove and refit n/s front undercarriage for replacement of parts.	1	\$ 200.00
6	To conduct computerized 4 wheel alignment.	0.5	\$ 100.00
7	Supply spray paint material and necessary items to respray affected area / panel.	4	\$ 800.00
Total labour			\$ 2,400.00
Estimate Grand Total			\$ 8,422.80

400l

20l

X

20l

180l

60l

55d

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____