



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SEDGWICK SINGAPORE PTE. LTD 30 CECIL STREET, LEVEL 12 PRUDENTIAL TOWER SINGAPORE 049712		Ref: CS3/SGK23000169/Rwy3e2 Date: 07/03/2023 Code: SGK	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	FORKLIFT	Veh. Inspected	XD 2853L
Policy No.		Coverage (\$)	0.00
Claim No.	6018297/ARI	Excess (\$)	0.00
Assign From	RAJADURAI ABRAHAM	Assign Date	05/01/2023
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI FP51JDR4RDEA	c.c	12882
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	FP51JDA00618	Colour	WHITE
Odometer	39305 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	ROADONE	8 mm
L/H Front Tyre	295/80 R22.5	ROADONE	8 mm
R/H Rear Tyre	295/80 R22.5 (D)	ROADONE	8/8 mm
L/H Rear Tyre	295/80 R22.5 (D)	ROADONE	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information			
Accident Date	19/11/2022	Inspection Date	06/01/2023
Survey held at	Sincere Garage Pte Ltd 48 Toh Guan Road, #02-126 Enterprise Hub, S608586		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$11,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	