



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 3588Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DRIVER DOOR	BENT	1,000.00	1,000.00
1	PASSENGER DOOR	BENT	1,000.00	1,000.00
1	FENDER (REAR)	BENT	1,200.00	945.00
2	BUMPER	MTG CRACKED	800.00	585.10
1	DRIVER POWER WINDOW	SERVICEABLE	600.00	-
2	PASSENGER POWER WINDOW	SERVICEABLE	600.00	-
1	DRIVER DOOR INNER TRIM	SERVICEABLE	500.00	-
1	PASSENGER DOOR INNER TRIM	SERVICEABLE	500.00	-
1	ALIGNMENT	NOT NECESSARY	80.00	-
1	WHEEL BEARING	NOT NECESSARY	500.00	-
1	RIM AND TYRE	SERVICEABLE	1,000.00	-
1	DRIVER DOOR HANDLE	SERVICEABLE	300.00	-
1	PASSENGER DOOR HANDLE	SERVICEABLE	300.00	-
1	DRIVER DOOR LOCK	TO REPAIR SEE LABOUR	600.00	-
1	PASSENGER DOOR LOCK	TO REPAIR SEE LABOUR	600.00	-
1	DRIVER REGULATOR	SERVICEABLE	1,200.00	-
1	PASSENGER REGULATOR	SERVICEABLE	1,200.00	-
1	BUMPER BRACKET	SERVICEABLE	300.00	-
	LESS 25% DISCOUNT		-	-882.52
			12,280.00	2,647.58
<u>LABOUR</u>				
	REMOVE AND REFIT REAR UNDERCARRIAGE.	NOT NECESSARY	500.00	-
	REMOVE AND REPLACE DAMAGED PARTS. }		1,000.00	800.00
	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIRS INCLUDING CUT AND WIELD, REALIGN BODY STRUCTURE. INCLUSIVE OF THE REPAIR OF DRIVER DOOR LOCK AND PASSENGER DOOR LOCK. }		1,200.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	900.00
			4,200.00	1,700.00
GRAND TOTAL			16,480.00	4,347.58
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (UNCONFIRMED)				3,450.00

Report Ref No. CS/FCI23000171/Kvy3m4

MARKET VALUE: \$5,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$526.00=NETT VALUE: \$4,974.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.