

AUTOLUTION
CARTIMES
 CarTimes Autolution Pte Ltd
 160 Sin Ming Drive AutoCity
 #02-04 Singapore 575722
 Tel : 6471 5111
 Email : claims@cartimes.com.sg

*Not Authorised
 Recovery By painting
 2 days
 \$1500.23*

VEHICLE NO: SNC2166K

MODEL: TOYOTA NOAH 1.8X

CHASSIS NO: ZWR800451044

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
PARTS (LIST ITEMS)	
FRONT BONNET <i>1055.30</i>	<i>AM</i> ✓ \$ 1,150.00
FRONT BONNET LOCK	<i>n</i> X \$ 180.00
FRONT BONNET HINGE LHS	<i>n</i> X \$ 85.00
FRONT BONNET HINGE RHS	<i>n</i> X \$ 85.00
FRONT GRILLE TOP WITH CHROME <i>345.00</i>	<i>CM</i> ✓ \$ 1,480.00
FRONT GRILLE ASSY (52711A)	<i>sn</i> X \$ 1,850.00
	<i>25%</i> \$ 4,830.00
	<i>20%</i> \$ 966.00
	\$ 3,864.00
SPECIAL NETT ITEMS	
FRONT BONNET INSULATOR CLIPS	<i>nn</i> \$ X 60.00
FRONT GRILLE CLIPS	<i>nn</i> \$ X 60.00
Total	\$ 120.00
TOTAL PARTS	\$ 3,984.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

☐ Weekend (\$

Not Authorised

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 200/ 1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 220/ 1,000.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100 100.00 X
4	To provide anti-rust treatment on affected areas	\$ 30/ 100.00
5	Dignostic Check	\$ 100 100.00 X
	Labour Total :	\$ 2,300.00
	TOTAL (PARTS & LABOUR):	\$ 6,284.00