

AUTOLUTION

CARTIMES

CarTimes Autolution Pte Ltd
160 Sin Ming Drive AutoCity
#02-04 Singapore 575722Tel : 6471 5111
Email : claims@cartimes.com.sgNot Authorised
Return by painting

2 days

\$1500.23

VEHICLE NO: SNC2166K

MODEL: TOYOTA NOAH 1.8X

CHASSIS NO: ZWR800451044

DESCRIPTION

REPAIRER'S
ESTIMATE(S\$)PARTS (LIST ITEMS)

FRONT BONNET 1055.30

FRONT BONNET LOCK

FRONT BONNET HINGE LHS

FRONT BONNET HINGE RHS

FRONT GRILLE TOP WITH CHROME 345.00

FRONT GRILLE ASSY (52711A)

By ✓ \$ 1,150.00

n X \$ 180.00

n X \$ 85.00

n X \$ 85.00

cm ✓ \$ 1,480.00

sn X \$ 1,850.00

25% \$ 4,830.00

20% \$ 966.00

\$ 3,864.00

SPECIAL NETT ITEMS

FRONT BONNET INSULATOR CLIPS

FRONT GRILLE CLIPS

nn \$ X 60.00

nn \$ X 60.00

Total \$ 120.00

TOTAL PARTS \$ 3,984.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ <i>200</i> 1,000.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ <i>220</i> 1,000.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ <i>nn</i> 100.00 X
4	To provide anti-rust treatment on affected areas	\$ <i>30</i> 100.00
5	Dignostic Check	\$ <i>nn</i> 100.00 X
	Labour Total :	\$ 2,300.00
	TOTAL (PARTS & LABOUR):	\$ 6,284.00