

SIN FATT DIESEL MOTOR

BLOCK 3020A UBI ROAD 1 #01-33 SINGAPORE 408714

SHUI KUN TIAN SHUI GUP & SNACKS
Blk 3020A Ubi Road 1
01-33
Singapore 408717

TP AIG.

23RD DECEMBER 2022

Xiao Tony

Accident date: 22th December 2022

Estimated repair cost for vehicle no: GBF3485J MERCEDES CITAN 109 CDI 2016

S/n	Qty	Items	U/price	Amount	
1	1	Rear boot lid -RH <i>Dented</i>		\$2,150.00	1100.
2	2	rear boot Lid hinges -RH <i>new</i>	\$188.00	\$376.00	X
3	1	Rear boot lid 109 logo		\$55.00	✓
4	1	Rear boot lid Emble logo		\$95.00	✓
5	1	Rear boot lid 70Km/h logo		\$30.00	✓
6	1	Rear boot lid CDI logo		\$35.00	✓
7	1	rear boot Lid 6 PAX		\$35.00	✓
8	1	Rear boot lid inner lock-RH <i>Damaged</i>		\$385.20	✓
9	1	Rear boot lid inner trim board-RH <i>new</i>		\$685.00	X
10	10	Rear boot lid inner clips -RH <i>new</i>	\$12.90	\$129.00	X
11	1	Rear boot lid inner rubber -RH <i>new</i>		\$255.20	X
12	1	Rear boot lid -LH <i>Distorted</i>		\$2,500.00	1550
13	1	Rear boot lid CITAN logo		\$55.00	✓
14		rear boot Lid cc logo		\$30.00	✓
15	1	Rear boot lid center moulding <i>Deformed</i>		\$258.00	✓
16	1	Rear boot lid inner lock-LH <i>Damaged</i>		\$385.20	✓
17	1	Rear boot lid inner trim board-LH <i>torn</i>		\$755.00	155
18	10	Rear boot lid inner clips -LH <i>new</i>	\$12.90	\$129.00	30
19	1	Rear boot lid inner rubber -LH <i>cut</i>		\$255.20	✓
20	2	rear boot Lid hinges -LH <i>new</i>	\$188.00	\$376.00	X
21	1	rear Boot Lid outer handle -lh <i>Damaged</i>		\$255.20	✓
22	2	Rear boot lid number plate lamp-LH	\$83.20	\$166.40	X
23	1	Rear boot lid number plate-LH		\$50.00	X
24	1	rear boot Lid number plate chrome -LH		\$115.00	X
25	1	boot lid windscreen -LH <i>Shattered</i>		\$1,420.00	750
26	1	boot lid windscreen rubber -LH <i>new</i>		\$285.10	X
27	1	windscreen seal-LH <i>new</i>		\$255.00	60
28	2	Rear tail lamp <i>cracked</i>	\$688.20	\$1,376.40	650
29	2	Rear tail lamp lower panel	\$315.20	\$630.40	X
30	2	Rear tail lamp lower panel bracket	\$131.75	\$263.50	X
31	2	tail lamp lower lamp	\$155.20	\$310.40	X
32	2	tail lamp lower cover	\$121.20	\$242.40	X
33	2	tail lamp inner panel	\$855.00	\$1,710.00	X
34	1	Rear bumper <i>Do hand</i>		\$955.00	✓
35	2	Rear bumper <i>Reinforcement</i>		\$550	✓
36	1	rear bumper side retainer <i>new</i>	\$185.00	\$185.00	✓
37	1	Rear bumper reverse sensor- set <i>Dmgd</i>		\$800.00	400
38	6	Rear bumper clips <i>new</i>	\$12.90	\$77.40	30
39	1	rear bumper towing cover -LH <i>new</i>		\$68.00	X
40	1	Rear end panel <i>Repair</i>		\$925.20	X
41	1	end panel top garnish <i>new</i>		\$315.20	X

Subtotal :-

\$19,329.40

Labour charges

To remove & re-fix rear windscreen -LH

\$120.00 ✓

Gum

\$50.00 ✓

To remove & re-fix rear reverse sensor

~~\$120.00~~ 50

To remove & re-fix rear cushion

1750 ~~\$120.00~~ 60

tuff Kote

~~\$150.00~~ 40

To check wiring system

~~\$60.00~~ 30

Panel beating

~~\$1,200.00~~ 700

Spray painting

~~\$1,200.00~~ 800

Subtotal :- \$3,020.00

Total:- \$22,349.40

Supplementary : 666.50

total : 9912.40

h/s : 7.9.10

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GBF3485J.

(Supplementary).

Rear Bumper Centre Guide. ^{and} 205. ✓

Rear Camera. Dgd

480. ✓

685

616.50

To remove rear camera

~~100.~~ 50

Supplementary: 666.50