



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP20003542790	Date of Loss:	12/12/2022
Vehicle Reg. No.:	SJA1161M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MUHAMMAD EKRAM BIN AZIMULLAH		
Make/Model:	MERCEDES-BENZ E250, 1.8 (A)	Vehicle Reg. Date:	30/11/2009
Vehicle Colour:	Metallic Brown		
Engine No:	27186030007944	Chassis No:	WDD2120472A94871
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS	Amount
Parts	4,844.40
Miscellaneous Items	0.00
Labour	670.00
Paintwork Labour	780.00
Towing	0.00
Gross Total (S\$)	6,294.40
+ GST 8.00% (S\$)	503.55
Nett Amount (S\$)	6,797.95

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2023)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT COVER	0.00	0.00	*1,480.00 F
2	1		*REAR BOOT REFLECTOR RH	0.00	0.00	*220.00 F
3	1		*REAR BOOT HINGE RH	0.00	0.00	*320.00 F
4	1		*REAR LAMP RH	0.00	0.00	*380.00 F
5	1		*REAR BUMPER	0.00	0.00	*779.00 F
6	1		*REAR BUMPER CHROME RH	0.00	0.00	*78.00 F
7	1		*REAR BUMPER CHROME LH	0.00	0.00	*78.00 F
8	1		*REAR BUMPER CEHROME CENTRE	0.00	0.00	*90.00 F
9	2		*REAR BUMPER SENSOR	0.00	0.00	*296.00 F
10	4		*REAR BUMPER SENSOR RING	0.00	0.00	*32.00 F
11	1		*REAR BUMPER SENSOR WIRE	0.00	0.00	*88.00 F
12	1		*REAR BUMPER TOW COVER	0.00	0.00	*40.00 F
13	1		*REAR BUMPER SIDE RETAINER RH	0.00	0.00	*23.00 F
14	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*450.00 F
15	10		*REAR BUMPER CLIP	0.00	0.00	*50.00 F

F=Franchise part.

Sub Total (\$\$)	4,404.00
+ Margin on L,N Items 10.00% (\$\$)	440.40
Total Parts (\$\$)	4,844.40

Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New	780.00
Labour Items			
2	TO CHECK WIRING SYSTEM	New	50.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	620.00
Gross Labour Cost (S\$)			1,450.00

Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >