

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 11 Jan 2023

Preliminary Advice

Vehicle No	: SJA1161M	Accident Date	: 12/12/2022
Make	: MERCEDES-BENZ E250	Policy No.	: SP2003542790
Assignment Date	: 06/01/2023	Excess	: S\$1,100.00
Date of Inspection	: DESKTOP SURVEY	Est. Duration of Repair	: 3
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) BLK 8 DEFU SOUTH STREET 1, DEFU INDUSTRIAL CITY #04-29 SINGAPORE 533758		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,294.40
Revised Amount	:S\$	4,608.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,608.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	25,525.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,475.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : *the vehicle repair on part by parts basis.due to no second parts available.*
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.