

A.S. P.C. BY:

REF:

CS/CS6/AIS 23000187 Dny

ASSIGNMENT

CDB Oct 2029

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: 1100

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 85K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 34 days Res.: Yes or No

Lum Sum: PIP % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJA 1161M Yr Regn: NOV / 2009

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E250 cc 1796

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 351360 T/Radio: Insured / Std / NI / NA

Eng/No: 27186030007944

C/No: WDD2120472A094871

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / W/Rim or

Tyre Size: F: 245/40 R18

R: 11

BS / DUN / EXNOVA / GY / P / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hexan

Front: _____ Rear: _____

R/Bal: S mm R/Bal: S mm

L/Bal: S mm L/Bal: S mm

D.O.A. 12/12/2022 D.O.I. 10/01/2023

Survey held at Desk Top

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	ALLING ALLING OD
	MV 851K
	LIA 25.51K
	4.4K 591K
07/06/23	Finalized PIP 4,223.90 with 3 days (Red, \$ 347.50, 45%)

Date/Time, File Pass to?

: Prel. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)

Survey Fee: _____

Transportation: _____

S + RS \$

Photos

Others

Report Format: _____

1 series, 2 cur, 1 P to 1 P

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jan 2023)
 Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BOOT COVER <i>new</i>	0.00	0.00	1,480.00 F	<i>new</i> X
2	1		*REAR BOOT REFLECTOR RH <i>new</i>	0.00	0.00	220.00 F	X
3	1		*REAR BOOT HINGE RH <i>new</i>	0.00	0.00	320.00 F	X
4	1		*REAR LAMP RH <i>new</i>	0.00	0.00	380.00 F	<i>new</i> X
5	1		*REAR BUMPER <i>new</i>	0.00	0.00	770.00 F	<i>new</i> X
6	1		*REAR BUMPER CHROME RH <i>broken</i>	0.00	0.00	78.00 F	<i>broken</i> X
7	1		*REAR BUMPER CHROME LH <i>new</i>	0.00	0.00	78.00 F	<i>new</i> X
8	1		*REAR BUMPER CECHROME CENTRE <i>broken</i>	0.00	0.00	90.00 F	<i>broken</i> X
9	2		*REAR BUMPER SENSOR <i>Down</i>	0.00	0.00	296.00 F	<i>Down</i> X
10	4		*REAR BUMPER SENSOR RING <i>new</i>	0.00	0.00	32.00 F	<i>new</i> X
11	1		*REAR BUMPER SENSOR WIRE <i>new</i>	0.00	0.00	88.00 F	<i>new</i> X
12	1		*REAR BUMPER TOW COVER <i>new</i>	0.00	0.00	40.00 F	<i>new</i> X
13	1		*REAR BUMPER SIDE RETAINER RH <i>new</i>	0.00	0.00	23.00 E	<i>new</i> X
14	1		*REAR BUMPER REINFORCEMENT <i>new</i>	0.00	0.00	450.00 F	<i>new</i> X
15	10		*REAR BUMPER CLIP <i>new</i>	0.00	0.00	50.00 F	<i>new</i> X
Sub Total (S\$)						4,404.00	
+ Margin on L,N Items 10.00% (S\$)						440.40	
Total Parts (S\$)						4,844.40	

F-1 franchise part.

Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

2129.00

+ 107.00 2341.90

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	780.00 500/-
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	50.00 30/-
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	620.00 500/-
Gross Labour Cost (S\$)			1,450.00

Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

10/01/2023 e form

NA Admin

Excess TBA

yn 2/sum

2 Kk Auto

8

3 days.

1030.00

3 371.90

sup 852.00

3/P 4,223.90

Bryan

97-37799

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SJA1161M/15/03/2023 12:28

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAIL LAMP LOWER SUPPORT RH <i>broken</i>	0.00	0.00	*45.00 F ✓
2	1		*TAIL LAMP LOWER SUPPORT LH <i>broken</i>	0.00	0.00	*45.00 F ✓
3	1		*BOOT LID INNER LOCK <i>1/4</i>	0.00	0.00	*230.00 F ✓
F=Franchise part.						
Sub Total (\$\$)						320.00
+ Margin on L,N Items 10.00% (\$\$)						32.00
Total Parts (\$\$)						352.00

Kan Fook Sing Motor Workshop/SJA1161M/15/03/2023 12:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES (REAR END PANEL & REAR FENDER)	New	550.00 <i>300/-</i>
Labour Items			
2	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR END PANEL & REAR FENDER)	New	500.00 <i>200/-</i>
Gross Labour Cost (\$\$)			1,050.00

Kan Fook Sing Motor Workshop/SJA1161M/15/03/2023 12:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KFS Motor

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

VEHICLE NO. : SJA1161M

ACCIDENT DATE : 12-12-2022 18:00

THIRD PARTY REF. : SHA2702U

INVOICE NO : TEST

DATE : 17-01-2023

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SJA1161M MERCEDES 250

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR LAMP RH	455.00
1	REAR BUMPER	770.00
1	REAR BUMPER CHROME RH	78.00
1	REAR BUMPER CHROME LH	78.00
1	REAR BUMPER CHROME CENTRE	90.00
1	REAR BUMPER SENSOR@\$148.00	148.00
1	REAR BUMPER REINFORCEMENT	460.00
10	REAR BUMPER CLIP@\$5.00	50.00
2	TAIL-LAMP LOWER SUPPORT @\$45.00	90.00
1	BOOT LID INNER LOCK	230.00
		2,449.00
	ADD 10 %	244.90
	TOTAL (A)	2,693.90

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	1000.00
1	SPRAYPAINTING CHARGES	1050.00
		2080.00

TOTAL (D)	
TOTAL REPAIR COST	: 14773.90
G S T %	: 293.91
EXCESS AMOUNT	: 1,100.00
INVOICE AMOUNT	: 3961.81