

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2023)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT COVER <i>Wt</i>	0.00	0.00	*1,480.00 F
2	1		*REAR BOOT REFLECTOR RH <i>H4</i>	0.00	0.00	*220.00 F
3	1		*REAR BOOT HINGE RH <i>H4</i>	0.00	0.00	*320.00 F
4	1		*REAR LAMP RH <i>white</i>	0.00	0.00	*380.00 F
5	1		*REAR BUMPER <i>force</i>	0.00	0.00	*779.00 F
6	1		*REAR BUMPER CHROME RH <i>broken</i>	0.00	0.00	*78.00 F
7	1		*REAR BUMPER CHROME LH <i>H4</i>	0.00	0.00	*78.00 F
8	1		*REAR BUMPER CEHROME CENTRE <i>broken</i>	0.00	0.00	*90.00 F
9	2		*REAR BUMPER SENSOR <i>Down</i>	0.00	0.00	*296.00 F
10	4		*REAR BUMPER SENSOR RING <i>H4</i>	0.00	0.00	*32.00 F
11	1		*REAR BUMPER SENSOR WIRE <i>H4</i>	0.00	0.00	*88.00 F
12	1		*REAR BUMPER TOW COVER <i>dislodged</i>	0.00	0.00	*40.00 F
13	1		*REAR BUMPER SIDE RETAINER RH <i>Sen</i>	0.00	0.00	*23.00 F
14	1		*REAR BUMPER REINFORCEMENT <i>Sen</i>	0.00	0.00	*450.00 F
15	10		*REAR BUMPER CLIP <i>H4</i>	0.00	0.00	*50.00 F

F=Franchise part.

Sub Total (S\$)	4,404.00
+ Margin on L,N Items 10.00% (S\$)	440.40
Total Parts (S\$)	4,844.40

Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAYPAINTING CHARGES	New	780.00 500/-
Labour Items			
2	TO CHECK WIRING SYSTEM	New	50.00 30/-
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	620.00 500/-
Gross Labour Cost (\$\$)			1,450.00

Kan Fook Sing Motor Workshop/SJA1161M/05/01/2023 15:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

10/01/2023 C Form

HA Admin

Excess TBA

 2/5/2023

2 Kk Auto



3
days.