

Case Details

Case Reference Number : TAX/01/23/2004
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1063G

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-20174-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited
 Accident Date and Time : 03/01/2023 07:15 AM
 Vehicle Age(In Months) : 61

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, RR BUMPER ASSY	1	478.90	478.90	25.00	359.17	Replace	1	0	Repair	RY
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xun
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xun
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	Xun
Standard	Main			PAD, RR BUMPER, CTR	3	2.50	7.50	25.00	5.63	Replace	0	0	Not Give	Xun
Standard	Main			RETAINER, RR BUMPER, RH	1	127.40	127.40	25.00	95.55	Replace	0	0	Not Give	Xun
Standard	Main			SEAL, RR BUMPER , RH	1	95.50	95.50	25.00	71.63	Replace	0	0	Not Give	Xun
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	ucl
Standard	Main			GUARD, RR BUMPER, LOWER	1	623.50	623.50	25.00	467.63	Replace	0	0	Not Give	Xun
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	Xun
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	943.10	943.10	25.00	707.33	Replace	1	0	Repair	RY
Standard	Main			PATCH, SIDE PANEL REAR END , RH & LH	1	37.70	37.70	25.00	28.28	Replace	0	0	Not Give	Xun

Total Spare Part Cost 2,083.89
 Lump Sum Discount (%) 20.00
 Final Spare Part Cost 1,576.46

Surveyor Total 36.00 ✓
 Lump Sum Dis (%) 20.00
 Final Sur Total 28.80

1/4/23, 3:53 PM

<https://vacswb.smrt.com.sg/Estimation.aspx>

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation		List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Surveyor Approval		Remarks
				Part Name	Qty	Price Per Unit(\$)							Repair/Replace		
Standard	Main			LINER, REAR FENDER, RH	1	151.10	151.10	25.00	113.32	Replace	0	0	Not Give	✓	Xun
									Total Spare Part Cost	2,083.89					
									Lump Sum Discount (%)	20.00					
									Final Spare Part Cost	1,576.46					
												Surveyor Total	36.00		
												Lump Sum Dis (%)			
												Final Sur Total	28.80		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	676.00	300	
Total:			676.00	300.00	✓

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR FENDER RH	378.00	200	
Total:			756.00	400.00	✓

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	Xun
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	Xun
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	Xun
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	Xun
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	Xun
Total:			500.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,576.46	28.80
Total Labour Cost	676.00	300.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spray Painting	756.00	400.00
Other	500.00	0.00
Overall Total	3,508.46	728.80
Lump Sum Repair Option	☐	☒
Lump Sum Total	3,500.00	750.00
Surveyor Approved Amount		750.00
No of Repair Days*	6	3
Remarks		LUMPSUM REPAIR / AFTER REPAIR PHOTOS, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR TAUFIKH HP 9749 5749 EMAIL: taufigh@lkkauto.com
Surveyor Name		Taufikh
Signature		
Survey Date	04/01/2023	

36
300
400
736
20% - 588.80
1/5 \$600
3 days

Taufikh 9749 5749
4/1/23
WP
cls resurvey after repair
3 days
taufikh@lkkauto.com

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: