

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/02/2023 User ID : PohSuan

	Section A - Accident Details
Registration Number	SHB1063G
Case Reference Number	TAX/01/23/2004
Registration Date	19/Dec/2017
Company Type	Strides Taxi Pte Ltd
Make	ТОУОТА
Model	PRIUS4
Name of Driver	SAMSUDIN BIN ALI
Type of Accident	Side Swipe
Accident Date and Time	3/Jan/2023 3:15 PM
Accident Reported Date and Time	3/Jan/2023 4:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117285
Special Instruction to ARC,if	RIGHT REAR PORTION
Prepared Date and Time	3/Jan/2023 5:42 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

	Section B - Summary of R	epair Estimates
Summary of Repair Estimate	es .	
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$2,083.89	\$36.00
Total Other Cost	\$500.00	(\$136.00)
TOTAL COST	\$4,015.89	\$600.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / NTUC
ARC / Surveyor Sign Off Date	04/01/2023 4:41 PM	04/01/2023 3:52 PM
Signature	-	
Remarks		LUMPSUM REPAIR / AFTER REPAIR PHOTOS, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR TAUFIKH, HP 9749 5749 EMAIL: taufikh@lkkauto.com



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated : 14/02/2023
User ID : PohSuan

	Section C - Quotation and Accident Invoice Details							
Quotation Number	QN-2301-0371	Invoice Number						
Quotation Date	31.01.2023	Invoice Date						
Invoice Amount		Prepared Date						

Section D - Details of Repair Estimates							
Part 1 - Labour Works							
Job Scope		Adjusted by Surveyor, if applicable					
TO REPAIR REAR PORTION RH	\$676.00	\$300.00					
Total Labour	\$676.00	\$300.00					

Part 2 - Spray Painting & Panel Beating Related Works						
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable				
TO RESPRAY REAR BUMPER	\$378.00	\$200.00				
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00				
Total Spray Painting & Panel Beating	\$756.00	\$400.00				

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO WASH AND VACUUM	\$60.00	\$0.00		
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00		
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00		
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00		
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00		
Lump Sum Adjustment by Surveyor	\$0.00	(\$136.00)		
Total Other Costs	\$500.00	(\$136.00)		

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
vumber		52159479	COVER, RR BUMPER ASSY	1.00	\$478.90	100.00	\$0.00	Replace	Repair	
		13	COVER, KIN BOWFER ASST	1.00	φ470.90	100.00	\$0.00	Treplace	IXepaii	
		52462470	PAD, RR BUMPER, RH & LH ,	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	_
		30	1	0.00	Ų	0.00	Ψ0.00	. topicae	1101 011011	
		52462470	PAD, RR BUMPER, RH & LH ,	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	_
		20	2		1				111111111	
		52462470	PAD, RR BUMPER, RH & LH,	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	
		10	3							
		52461470	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given	
		10								
		1	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	
		40								
			SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given	
		50		ļ				<u>_</u>	_	_
			CLIPS PIECE, FRT & RR	10.00	\$4.80	25.00	\$36.00	Replace	Replace	
		10	BUMPER	0.00	0000 50	0.00	#0.00		N + O	_
		52453470	GUARD, RR BUMPER,	0.00	\$623.50	0.00	\$0.00	Replace	Not Given	
		10	LOWER SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	_
			SENSOR REVERSE	0.00	\$100.00	0.00	\$0.00	Replace	Not Given	
		61601471	PANEL SUB-ASSY, FENDER	1.00	\$943.10	100.00	\$0.00	Replace	Repair	
		50	REAR RH	1.00	ψ943.10	100.00	Ψ0.00	Teplace	Repair	
		65565470	PATCH, SIDE PANEL REAR	0.00	\$37.70	0.00	\$0.00	Replace	Not Given	_
		10	END . RH & LH		1,		45.00	opiaoo	1.50	
		65637470	LINER, REAR FENDER, RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	_
		60	,					' """	1	
Total					\$2,657.40		\$36.00			_



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated : 14/02/2023
User ID : PohSuan

Added Sp	Added Spare Parts / Material Usage After Surveyor Signed off								
Part Number									
Total		rtamoi				(70)			

	36.00	
+	300.00	L/S \$600/-
+	400.00	
	736.00	
	-20%	
	588.80	