



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000189/Kny3e2 Date: 12/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	S 3609CD	Veh. Inspected	SMS 2571B	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS23/0065	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	06/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	GP71218089	Colour	METALLIC SILVER	
Odometer	175643 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	FIRENZA	8 mm	
L/H Front Tyre	185/60 R15	FIRENZA	8 mm	
R/H Rear Tyre	185/60 R15	FIRENZA	8 mm	
L/H Rear Tyre	185/60 R15	FIRENZA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE VEHICLE HAD COMMENCED ITS REPAIR WORK AT THE TIME OF INSPECTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/12/2022	Inspection Date	06/01/2023	
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a. Remarks				
A)REGISTRATION DATE: 18 FEB 2020 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		