



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23000195/Rvy3m4 Date: 09/03/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 1920H	Veh. Inspected	SNH 549B
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/12/22/2061	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	06/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI IONIQ EV FL	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	KMHC851JUNU089876	Colour	RED
	Odometer	7987 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	MICHELIN	6 mm
	L/H Front Tyre	205/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	205/60 R16	MICHELIN	6 mm
	L/H Rear Tyre	205/60 R16	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/12/2022	Inspection Date	06/01/2023
	Survey held at	KOMOCO MOTORS PTE LTD 253 ALEXANDRA ROAD #01-01 SINGAPORE 159936.		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	