



KOMOCO MOTORS PTE. LTD.

21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100

(GST REGISTRATION NO: MR-8500364-4)

Date : 05/01/2022

MS First Capital Insurance Ltd

Attn: Motor Claims Department

Vehicle number : **SNH549B**

Make and model : IONIQ ELECTRIC

Registration Date : 23/09/2022

Chassis number : KMHC851JUNU089876

Engine number : EM10N5P0044J

Job No. :

Owner name : KOMOCO CAR

Date of Acc : 21/12/2022

Policy number : CN176488

Claim Type : TP CLAIM

Items :

Estimate

1	BUMPER CLIP X10 <i>sub</i>	86595-2T500	\$	12.00	✓
2	COVER-FR BUMPER <i>sub</i>	86511-G2500	\$	452.40	481.10
3	MOULDING-FRONT BUMPER CTR,UPR <i>sub</i> <i>nn</i>	86585-G7500	\$	138.30	×
4	MOULDING-FRONT BUMPER,RH <i>sub</i>	86564-G2550	\$	93.00	✓
5	LAMP ASSY-DAY RUNNING LIGHT,RH <i>? Xnn</i>	92208-G2100	\$	642.50	×
6	BRACKET-FR BUMPER SIDE SUPT,RH <i>? Xnn</i>	86556-G2000	\$	12.00	×
7	BRACKET-FR BUMPER SIDE,RH <i>? Xnn</i>	86514-G2000	\$	28.00	×
8	LAMP ASSY-HEAD,RH <i>nn</i>	92102-G2230	\$	2,110.30	✓

Less 20% Discount

Material total

\$ 3,488.50

\$ 697.70

\$ 2,790.80

Vehicle number : **SNH549B**
Make and model : **IONIQ ELECTRIC**
Registration Date : **23/09/2022**
Chassis number : **KMHC851JUNU089876**
Engine number : **EM10N5P0044J**

Job No. :
Owner name : **KOMOCO CAR**
Date of Acc : **21/12/2022**
Policy number : **CN176488**
Claim Type : **TP CLAIM**

Body, Paint & Labour Items :

Estimate

1 To carry out accident body repair

\$ ~~840.00~~ **420** ✓

2 Complete putty and spray paint all affected areas

\$ ~~760.00~~ **525.10** ✓

Labour Charges:

Estimate

3 To supply & install Front number plate (S.NETT)

\$ ~~40.00~~ **X 12**

Total

\$ 4,430.80

Excess

Add GST 7%

\$ 310.16

Grand Total

\$ 4,740.96

*** *Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out****

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

3 days

P/P

06/01/23 @ 1535

Rey before print

email: rasul@lkkauto.com