



KOMOCO MOTORS PTE. LTD.
232 Alexandra Road #01-01 Singapore 119936
Tel: 65616475 Fax: 6564721613 Email: kmo@komoco.com.sg
GST No: 100009538

(GST REGISTRATION NO: MR-8500364-4)

Date : 05/01/2022

MS First Capital Insurance Ltd

Attn: Motor Claims Department

Vehicle number : **SNH549B**
Make and model : IONIQ ELECTRIC
Registration Date : 23/09/2022
Chassis number : KMHC851JUNU089876
Engine number : EM10N5P0044J

Job No. :
Owner name : KOMOCO CAR
Date of Acc : 21/12/2022
Policy number : CN176488
Claim Type : TP CLAIM

Items :		Estimate	
1	BUMPER CLIP X10	86595-2T500	\$ 12.00
2	COVER-FR BUMPER	86511-G2500	\$ 452.40
3	MOULDING-FRONT BUMPER CTR,UPR	86585-G7500	\$ 138.30
4	MOULDING-FRONT BUMPER,RH	86564-G2550	\$ 93.00
5	LAMP ASSY-DAY RUNNING LIGHT,RH	92208-G2100	\$ 642.50
6	BRACKET-FR BUMPER SIDE SUPT,RH	86556-G2000	\$ 12.00
7	BRACKET-FR BUMPER SIDE,RH	86514-G2000	\$ 28.00
8	LAMP ASSY-HEAD,RH	92102-G2230	\$ 2,110.30

	\$ 3,488.50
Less 20% Discount	\$ 697.70
Material total	<u>\$ 2,790.80</u>

Vehicle number : **SNH549B**
Make and model : IONIQ ELECTRIC
Registration Date: 23/09/2022
Chassis number : KMHC851JUNU089876
Engine number : EM10N5P0044J

Job No. :
Owner name : KOMOCO CAR
Date of Acc : 21/12/2022
Policy number : CN176488
Claim Type : TP CLAIM

Body,Paint & Labour Items :		Estimate
1	To carry out accident body repair	\$ 2,100.00
2	Complete putty and spray paint all affected areas	\$ 1,900.00
Labour Charges:		Estimate
3	To realign both REAR Tail lamp (S.NETT)	\$ 40.00
4	To supply & install REAR number plate (S.NETT)	\$ 40.00
5	To repair chassis member (S.NETT)	\$ 420.00
6	To put on chassis bench aligner (S.NETT)	\$ 420.00
7	To R&I rear Compartment Trim & Lining	\$ 420.00
8	To Transfer rear Tailgate mechanism	\$ 180.00
Total		<u>\$ 8,310.80</u>
Excess		
Add GST 7%		\$ 581.76
Grand Total		<u>\$ 8,892.56</u>

*** *Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out****