

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/11/2022

User ID : JeongCH

Section A - Accident Details	
Registration Number	SMB1442L
Case Reference Number	BUS/11/22/5035
Registration Date	8/7/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Kerh Tien Kiat
Type of Accident	Side Swipe
Accident Date and Time	11/21/2022 1:32 PM
Accident Reported Date and Time	11/30/2022 11:04 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB1442L - Right front body panel cracked SMU7016U (TP) - INSURED WITH INCOME
Prepared Date and Time	11/30/2022 1:37 PM
Chassis Number	WMAA22ZZ2E7002183
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$2,507.54	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,010.54	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	30/11/2022 1:43 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/11/2022

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$795.00					
Total Labour				\$795.00					
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$708.00				530	
Total Spray Painting & Panel Beating				\$708.00				538	
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010152	Body	F01001-CW266	COVER,HEADLAMP:FRT ,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	✓
6010305	VE	81.25101-6540	HEADLAMP,RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	✓
6010307	VE	81.25320-6112	FLASHER,AUX HEADLAMP,RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	✓
Total					\$3,482.70		\$3,134.43		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



2 Days

Lumpsum repair

Guo Qiang - LKK

30/11/2022