



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS/ASM23000214/Kqp3e2

10 MARINA BOULEVARD  
#48-01 MARINA BAY FINANCIAL CENTRE TOWER  
2SINGAPORE 018983

Date: 02/02/2023

ATTN: KHOR SAW THENG

Code: HSB

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 633Z	<b>Veh. Inspected</b>	SKZ 1722B
<b>Policy No.</b>	VFX/P2419140	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M04F9H	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	KHOR SAW THENG	<b>Assign Date</b>	06/01/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA WISH (A)	<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>	ZGE206026262	<b>Colour</b>	METALLIC BROWN
<b>Odometer</b>	150124 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/55 R15	NEUTON	7 mm
<b>L/H Front Tyre</b>	195/55 R15	NEUTON	7 mm
<b>R/H Rear Tyre</b>	195/55 R15	NEUTON	3 mm
<b>L/H Rear Tyre</b>	195/55 R15	NEUTON	3 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/11/2022	<b>Inspection Date</b>	06/01/2023
<b>Survey held at</b>	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**