



Notification Letter

Date : 05/01/2023

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
3 ANSON ROAD
#16-00, SPRINGLEAF TOWER
079909

Dear Sir / Madam,

We are instructed by **ETHOZ PROTECT PTE LTD** to notify you of a road traffic accident on **03/12/2022** at about **19:00** at **MARINA BOULEVARD** involving our client's/ customer vehicle registration number **GBH- 918-L** and vehicle registration number **SMC8901C** driven by you at the material time.

A copy of Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's/ customer's vehicle has been damaged. Before our we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

Cc (other insurance companies for chain collision accident)

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 05/01/2023

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department** **FAX :**

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : 1 Accident Date : 03/12/2022
Vehicle No : GBH- 918-L Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	SLIDING DOOR LH	980.00	
1	ROCKER PANEL LH	RESTORE	
1	REAR FENDER LH	RESTORE	
Sub Total		980.00	
Discount 25% On Parts		(245.00)	
Special Nett Item			
1	ADVERTISEMENT STICKER PANELS LH	1,000.00	

Date : 05/01/2023

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department** FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 03/12/2022

Vehicle No : GBH- 918-L Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1000.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	600.00	
	TO RESPRAY AFFECTED AREAS	600.00	
	TO REMOVE AND TRANSFER DOOR COMPONENTS	150.00	
	RUST PROOFING	50.00	
	Sub Total	1400.00	

3,135.00

Remarks:

SUB TOTAL

GST 7.0 % 219.45

TOTAL 3,354.45

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____