



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB22010737/Dqy3e2-1	
			Date: 11/01/2023	
			Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 2516Y	Veh. Inspected	SDU 57D
	Policy No.	D21MFL0000447_01	Coverage (\$)	0.00
	Claim No.	MFL2022D0006475	Excess (\$)	0.00
	Assign From	GABRIEL WEE	Assign Date	06/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E250	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDD2130452A590316	Colour	GREY
	Odometer	55062 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40Z R19	ARIVO	6 mm
	L/H Front Tyre	245/40Z R19	ARIVO	6 mm
	R/H Rear Tyre	275/35Z R19	ARIVO	6 mm
	L/H Rear Tyre	275/35Z R19	ARIVO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/10/2022	Inspection Date	28/10/2022
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	