



Case Details

Case Reference Number : TAX/11/22/2051
Type of Repair : Accident Repair
Vehicle Registration Number : SHB178R

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-19916-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited
Accident Date and Time : 25/11/2022 02:40 PM
Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	1	682.63	Replace	✓
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	1	207.61	Replace	✓
Standard	Main			FINISHER-RR BPR - RH	1	47.42	47.42	10.00	42.68	Replace	0	0.00	Not Give	✗
Standard	Main			FINISHER-RR BPR - LH	1	47.42	47.42	10.00	42.68	Replace	0	0.00	Not Give	✗
Standard	Main			BRACKET ASM-RR BPR FASCIA SI-RH	1	29.85	29.85	10.00	26.87	Replace	0	0.00	Not Give	✗
Standard	Main			BRACKET ASM-RR BPR FASCIA SI - LH	1	29.84	29.84	10.00	26.86	Replace	0	0.00	Not Give	✗
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - LH	1	46.08	46.08	10.00	41.47	Replace	0	0.00	Not Give	✗
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - LH	1	13.20	13.20	10.00	11.88	Replace	0	0.00	Not Give	✗
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - CTE	1	12.90	12.90	10.00	11.61	Replace	0	0.00	Not Give	✗
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - RH	1	12.90	12.90	10.00	11.61	Replace	0	0.00	Not Give	✗
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - RH	1	12.80	12.80	10.00	11.52	Replace	0	0.00	Not Give	✗
Total Spare Part Cost									2,450.84	Surveyor Total 890.24				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0.00				
Final Spare Part Cost									2,450.84	Final Sur Total 890.24				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - LH	1	12.80	12.80	10.00	11.52	Replace	0	0.00	Not Give ✓	X <i>nn</i>
Standard	Main			BAR ASM-RR BPR IMP	1	339.76	339.76	10.00	305.78	Replace	0	0.00	Check ✓	?
Standard	Main			LAMP ASM-RR FOG - RH	1	189.07	189.07	10.00	170.16	Replace	0	0.00	Not Give ✓	X <i>nn</i>
Standard	Main			LAMP ASM-RR FOG - LH	1	36.30	36.30	10.00	32.67	Replace	0	0.00	Not Give ✓	X <i>nn</i>
Standard	Main			SENSOR-RR PARK DIST CONT	3	68.00	195.00	10.00	175.50	Replace	0	0.00	Check ✓	?
Standard	Main			PANEL ASM- RR END	1	708.66	708.66	10.00	637.79	Replace	1	0.00	Repair ✓	X <i>pe</i>
Total Spare Part Cost									2,450.84	Surveyor Total 890.24				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0.00				
Final Spare Part Cost									2,450.84	Final Sur Total 890.24				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,200.00	500.00	
Total:			1,200.00	500.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	220.00	
2	Main	TO RESPRAY REAR BUMPER REINFORCEMENT	230.00	0.00	X <i>nn</i>
3	Main	TO RESPRAY REAR PANEL	230.00	150.00	
Total:			888.00	370.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00	X <i>nn</i>
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40.00	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	X <i>nn</i>
4	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150.00	
Total:			1,000.00	340.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
6	Main	TO WASH AND VACUUM	60.00	0.00	X
7	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	X
Total:			1,000.00	340.00	San

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,450.84	890.24
Total Labour Cost	1,200.00	500.00
Total Spray Painting	888.00	370.00
Other	1,000.00	340.00
Overall Total	5,538.84	2,100.24
Lump Sum Repair Option		☐
Lump Sum Total	0.00	2,100.24
Surveyor Approved Amount		2,100.24
No of Repair Days*	5	4
Remarks	-	PART BY PART / BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM. PLEASE CALL SURVEYOR quoqiang (LKK) & Email: quoqiang@lkkauto.com.sg 87880727
Signature		GuoQiang
Survey Date	28/11/2022	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display the car during resurvey
- Parts provided for confirmation
- Third party claims on a "Without Prejudice" basis
- No legal action(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by _____

Signature: _____

Date: _____